

From: Shad Brown  
 Sent: Friday, January 30, 2026 3:34 PM  
 To: Tammy Jones; Bob Percell; Clint Calvert; Freddy Proctor; Jennifer Street; Priscilla Shorty  
 Subject: Re: HUBER-NELSON 2-31 - INC - 719001246  
 Attachments: IMG\_1788.jpeg; IMG\_1791.jpeg; IMG\_1790.jpeg; IMG\_1789.jpeg

Impacted soil has been removed and replaced with clean fill.

Shad Brown  
 Area 1  
 505-609-3449  
 505-634-8207

From: Tammy Jones <tajones@hilcorp.com>  
 Sent: Wednesday, January 28, 2026 6:53:01 AM  
 To: Bob Percell <bpercell@hilcorp.com>; Clint Calvert <Clint.Calvert@hilcorp.com>; Freddy Proctor <fproctor@hilcorp.com>; Jennifer Street <jstreet@hilcorp.com>; Priscilla Shorty <pshorty@hilcorp.com>; Shad Brown <shbrown@hilcorp.com>; Tammy Jones <tajones@hilcorp.com>  
 Subject: HUBER-NELSON 2-31 - INC - 719001246

<b>Today's Date:</b>	1/28/2026				
<b>Well Name:</b>	HUBER-NELSON 2-31	<b>Location:</b>	Sec: 31	Twn: 035N	Rng: 0
<b>API Number:</b>	05.067.07789	<b>Footage:</b>	1220' FNL & 1720' FWL		
<b>Operator:</b>	Hilcorp Energy Company	<b>Area/Run/MSO:</b>	01	0100	Bob Pe
<b>Meter #:</b>	DR0509RP		<b>Pipeline:</b>	HEC	
<b>INC Number:</b>	719001246	<b>Agency:</b>	ECMC	<b>Inspector:</b>	CHARL
<b>Type of INC:</b>	Written	<b>Photos Required:</b>	<b>Yes</b>	<b>Due Date:</b>	
<b>Issue of Concern:</b>	<p>LOCATION SIGN ON SEPARATOR BUILDING HAS NO API#. <b>Install sign per rule 605 - DUE DATE: 01/30/2026</b></p> <p>PC UNIT NOT RUNNING HOWEVER THERE APPEARS TO HAVE BEEN A HYDRAULIC LEAK ONTO GRO...          WELLHEAD SEE LOCATION PICTURES. <b>MAINTAIN ENGINE RULE 608.e AND CLEAN UP IMPACTED</b>  <b>WELLHEAD rule 1002.f - DUE DATE: 01/30/2026</b></p> <p>EROSION STARTING TO OCCUR ON SOUTH EAST CORNER OF PAD CHECK DAM WASHED OUT SE...          PICTURES. <b>Install or repair required BMPs per Rule 1002.f.(2)C - DUE DATE: 02/03/2026</b></p>				



From: Shad Brown <shbrown@hilcorp.com>

Sent: Wednesday, February 4, 2026 7:04 AM

To: Tammy Jones <tajones@hilcorp.com>; Bob Percell <bpercell@hilcorp.com>; Clint Calvert <Clint.Calvert@hilcorp.com>; Freddy Proctor <fproctor@hilcorp.com>; Jennifer Street <jstreet@hilcorp.com>; Priscilla Shorty <pshorty@hilcorp.com>

Subject: RE: HUBER-NELSON 2-31 - INC - 719001246

EROSION STARTING TO OCCUR ON SOUTHEAST CORNER OF PAD CHECK DAM WASHED OUT SEE LOCATION PICTURES. Install or repair required BMPs per Rule 1002.f.(2)C - **DUE DATE: 02/03/2026**

**Erosion issues have been addressed.**



Shad Brown

Area 1

505-609-3449

505-634-8207



**From:** Shad Brown <shbrown@hilcorp.com>  
**Sent:** Tuesday, February 17, 2026 11:57 AM  
**To:** Tammy Jones <tajones@hilcorp.com>; Bob Percell <bpercell@hilcorp.com>; Clint Calvert <Clint.Calvert@hilcorp.com>; Freddy Proctor <fproctor@hilcorp.com>; Jennifer Street <jstreet@hilcorp.com>; Priscilla Shorty <pshorty@hilcorp.com>  
**Subject:** Re: HUBER-NELSON 2-31 - INC - 719001246

New sign

Shad Brown  
Area 1  
505-609-3449  
505-634-8207

