

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404547768

Date Received:  
02/17/2026

**FIR RESOLUTION FORM**

**Overall Status:**

CA Summary:  
3 of 3 CAs from the FIR responded to on this Form  
3 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 10133  
Name of Operator: HILCORP ENERGY COMPANY  
Address: P O BOX 61229  
City: HOUSTON State: TX Zip: 77208  
Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

**Additional Operator Contact:**

| Contact Name     | Phone | Email                                 |
|------------------|-------|---------------------------------------|
| Labowskie, Steve |       | steve.labowskie@state.co.us           |
| .General         |       | FarmingtonRegulatoryTechs@hilcorp.com |

**ECMC INSPECTION SUMMARY:**

FIR Document Number: 719001246  
Inspection Date: 01/27/2026 FIR Submit Date: 01/27/2026 FIR Status:

**Inspected Operator Information:**

Company Name: HILCORP ENERGY COMPANY Company Number: 10133  
Address: P O BOX 61229  
City: HOUSTON State: TX Zip: 77208

**LOCATION - Location ID: 326292**

Location Name: HUBER-NELSON-N35N8W Number: 31NENW County: LA PLATA  
Qtrqtr: NENW Sec: 31 Twp: 35N Range: 8W Meridian: N  
Latitude: 37.262540 Longitude: -107.789750

**FACILITY - API Number: 05-067-00 Facility ID: 216183**

Facility Name: HUBER-NELSON Number: 2-31  
Qtrqtr: NENW Sec: 31 Twp: 35N Range: 8W Meridian: N  
Latitude: 37.262540 Longitude: -107.789750

**CORRECTIVE ACTIONS:**

1 CA# 210657

Corrective Action: Install sign per rule 605 Date: 02/03/2026

Response: CA COMPLETED Date of Completion: 02/17/2026

Operator Comment: New sign installed - see attached photo

ECMC Decision:

ECMC  
Representative:

2 CA# 210658

Corrective Action: MAINTAIN ENGINE RULE 608.e AND CLEAN UP IMPACTED SOIL AROUND  
WELLHEAD rule 1002.f

Date: 01/30/2026

Response: CA COMPLETED

Date of Completion: 01/30/2026

Operator  
Comment: Impacted soil removed and replaced with clean fill - see attached photos

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

3 CA# 210659

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 02/03/2026

Response: CA COMPLETED

Date of Completion: 02/03/2026

Operator  
Comment: Erosion issues addressed - see attached photos

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: RESOLVED - see attached photos

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tammy Jones

Signed: \_\_\_\_\_

Title: Ops/Regulatory Tech

Date: 2/17/2026 12:29:26 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u>       |
|------------------------|--------------------------|
| 404547768              | FIR RESOLUTION SUBMITTED |
| 404547785              | Resolved Photos          |

Total Attach: 2 Files