

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404550879

Date Received:  
02/19/2026

**FIR RESOLUTION FORM**

**Overall Status:**

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Coleman, Chris</u>		<u>chris.coleman@state.co.us</u>
<u>.TEP</u>		<u>COGCCInspectionReports@terraep.com</u>

**ECMC INSPECTION SUMMARY:**

FIR Document Number: 719200036  
Inspection Date: 06/13/2025 FIR Submit Date: 07/29/2025 FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

**LOCATION** - Location ID: 423439

Location Name: Miller Number: 67S91W County: \_\_\_\_\_  
Qtrqtr: NWSE Sec: 6 Twp: 7S Range: 91W Meridian: 6  
Latitude: 39.476792 Longitude: -107.594923

**FACILITY** - API Number: 05-045- -00 Facility ID: 423439

Facility Name: Miller Number: 67S91W  
Qtrqtr: NWSE Sec: 6 Twp: 7S Range: 91W Meridian: 6  
Latitude: 39.476792 Longitude: -107.594923

**CORRECTIVE ACTIONS:**

**1** CA# 206522

Corrective Action: Comply with Rule 606.a and remove unused equipment. Date: 08/11/2025

Response: CA COMPLETED Date of Completion: 09/10/2025

Operator Comment: Corrective action completed. Tank was removed and/or reconnected. This corrective action is complete.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

2 CA# 206523

Corrective Action: Conduct additional interim reclamation in accordance with ECMC 1003 series rules. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of pre-disturbance area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local soil conservation district. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until Final Reclamation has passed.

Date: \_\_\_\_\_

Response: CA COMPLETED

Date of Completion: 02/19/2026

Operator Comment: TEP has solicited bids for performing additional reclamation work at this location. Work is scheduled to be completed during the spring / summer months of 2026. An additional FIRR will be submitted once the work has been completed to document that this corrective action has been closed.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been completed.

CA 206523: TEP has solicited bids for performing additional reclamation work at this location. Work is scheduled to be completed during the spring / summer months of 2026. An additional FIRR will be submitted once the work has been completed to document that this corrective action has been closed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: \_\_\_\_\_

Title: TEP Environmental Lead

Date: 2/19/2026 11:41:53 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

404550879	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files