

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404552268

Date Received:  
02/20/2026

**FIR RESOLUTION FORM**

**Overall Status:**

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 10758  
Name of Operator: OGRIS OPERATING LLC  
Address: PO BOX 53467  
City: MIDLAND State: TX Zip: 79710

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Giena, Zeches</u>		<u>gzeches@ogrisop.com</u>
<u>Sanchez, Chris</u>		<u>chris.sanchez@state.co.us</u>

**ECMC INSPECTION SUMMARY:**

FIR Document Number: 713602569  
Inspection Date: 12/30/2025 FIR Submit Date: 12/31/2025 FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: OGRIS OPERATING LLC Company Number: 10758  
Address: PO BOX 53467  
City: MIDLAND State: TX Zip: 79710

**LOCATION** - Location ID: 308857

Location Name: GOLDEN EAGLE-633S67W Number: 22SWNW County: LAS ANIMAS  
Qtrqtr: SWN Sec: 22 Twp: 33S Range: 67W Meridian: 6  
W  
Latitude: 37.158380 Longitude: -104.882290

**FACILITY** - API Number: 05-071- -00 Facility ID: 283707

Facility Name: GOLDEN EAGLE Number: 22-05X  
Qtrqtr: SWN Sec: 22 Twp: 33S Range: 67W Meridian: 6  
W  
Latitude: 37.158380 Longitude: -104.882290

**CORRECTIVE ACTIONS:**

**1** CA# 210211

Corrective Action: Report spill or release of E&P waste or produced fluids in accordance with Rule 912.b. Contact ECMC EPS staff per Rule 912.b. Date: 05/15/2025

Response: OTHER

Operator Comment: ECMC official Chris Sanchez was notified on 5/15/2025 of the discovered spill on location. Per the email, it was explained that during the initial spill investigation it was determined that the area of impacted soil was less than the 10 cubic yard reportable limit. Please see attached copy of email correspondence. All stained material has

since been removed from location and there is an ongoing soil sampling investigation, which will be continued to be included on upcoming Form27 supplemental reports.

ECMC Decision: \_\_\_\_\_

ECMC Representative:

**2** CA# 210212

Corrective Action: Operator shall provide Quarterly Reporting until the Site Assessment is completed and the remediation area demonstrates Compliance with Table 915-1 Standards. Comply with Rule 912.b. and form 27i (404133910) Conditions of Approval.

Date: 01/02/2026

Response: CA COMPLETED

Date of Completion: 01/05/2026

Operator Comment: SEE Form27S DOC#40493427

ECMC Decision: \_\_\_\_\_

ECMC Representative:

**3** CA# 210213

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 01/31/2026

Response: OTHER

Operator Comment: This is an on-going active reclamation process. The location was initially reclaimed summer of 2025 and not long after we recieved heavy rains that had caused rilling and errosion. The location was once again graded and hydro mulched and is in need of the same treatment currently. We are currently waiting on equipment repairs but this location will continue to be maintained. An update to this FIRR will be provided once the planned work is complete.

ECMC Decision: \_\_\_\_\_

ECMC Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: FURTHER UPDATE WILL BE PROVIDED THROUGH UPCOMING FORM 27S FOR ALL LOCATION UPDATES.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: GIENA ZECHES

Signed: \_\_\_\_\_

Title: ENVIRONMENTAL

Date: 2/20/2026 10:44:23 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
404552268	FIR RESOLUTION SUBMITTED
404552379	PHOTO LOG
404552381	EMAIL CORRESPONDANCE

Total Attach: 3 Files