

JOB LOG

WELL NO. CU LEASE LEN TICKET NO. 402116
 CU AER Barnesville Swals PAGE NO. 1 OF
 JOB TYPE 5/8 E-Z-SV FOR Plug and Abandon 8-27-92

FORM 2013 R-2

CHART NO.	TIME	RATE (BPM)	VOLUME (BBL) (GAL)	PUMPS		PRESSURE (PSI)		DESCRIPTION OF OPERATIONS & MATERIALS
				T	C	TUBING	CASING	
	09:30							on Location
	09:40							pick up string tool & E-Z-SV
	09:42							make dummy run
	09:44		129					Set E-Z-SV @ 7236' + Load Csg.
	10:42							Released for day 8-28-92
	07:00							on Location
	09:30		2					Load Csg.
	09:40					500		Test Csg.
	10:36							Good Test
	10:38					3000	500	Test Tubing Good Test
	11:38	1.8	0			2600	500	est. injection test
	11:46					2450	500	Start mixing cat 32 slts - drop
							500	6 slts on top of Retainer
								pull 35 slts. mix 9" pos. out
	11:50					2450	500	end mixing
	12:00					2450	500	Start disp.
	12:30					2150	500	end disp.
	12:41							pull 3 slts
	12:52							Start mixing 9" pos
	14:10					1000		Set 100' plug c. 5519-5449'
	14:25					1100		plug down pull up to surface
	1325		1.2					Set 50' Surface 9/29 end pumping
	1335		0					Runp 50 slts down 8 1/2" x 1 1/2"
	1340		0					End pump
	1345		0					Runp 50 slts down 8 1/2" x 1 1/2"
	1359		0					End pump
								Released for day

FIELD COPY
NOT AN INVOICE
 Released for day

Thinks
John



CUSTOMER

103-08936