

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/19/2026

Submitted Date:

02/19/2026

Document Number:

716302000

FIELD INSPECTION FORM

Loc ID 333871 Inspector Name: Beardslee, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10705
Name of Operator: EVERGREEN NATURAL RESOURCES LLC
Address: 1775 SHERMAN ST. #2775
City: DENVER State: CO Zip: 80203

Findings:

- 13 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Distribution, Evergreen	719-846-7898	cogcc.evergreen@enrllc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
263137	WELL	PR	01/27/2003	CBM	071-07610	BOUNCER 41-27	PR
275633	WELL	PR	03/12/2005	CBM	071-08291	BOUNCER 41-27 TR	PR

General Comment:

"This is a field audit of the scout card, related documents and the location."

Location

Lease Road:			
Type			
comment:			
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:	PHOTO 7: NO NFPA STICKER POSTED, NO CAPACITY POSTED AND CONTENTS IS PRODUCED WATER NOT NONE POTABLE WATER.		
Corrective Action:	REMOVE OR COVER NONE POTABLE WATER STICKER AND POST TANK BATTERY SIGHS PER RULE 605. CA DATE 3/3/2026.	Date:	03/03/2026

Emergency Contact Number:		
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: _____

Good Housekeeping:			
Type	TRASH		
Comment:	PHOTO 6: TRASH OFF THE NORTH SIDE OF LOCATION APPEARS TO BE INSULATION FROM SOUND WALLS.		
Corrective Action:	REMOVE TRASG ON AND AROUND LOCATION PER RULE 606.	Date:	02/25/2026

Overall Good:

Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			

Equipment:			corrective date
Type: Prime Mover	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	BOTH ARE ACCESSABLE		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 6		
Comment:			
Corrective Action:		Date:	
Type: Progressive Cavity	# 2		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		

Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	BOTH CAL. REPORTS INDICATE GAS METERS HAVE BEEN CALIBRATED WITHIN THE LAST YEAR.		
Corrective Action:		Date:	
Type: Vertical Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:	TR WELL FORM 4 VACUUM SUNDRY #402103135		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	FIBERGLASS AST		37.222763,-104.871332
Comment:	PHOTO 8: HATCH ON TANK IS OPEN WITH NO BIRD PROTECTION.				
Corrective Action:	PLUMB 2" PIPE SO HATCH CAN BE CLOSED OR INSTALL BIRD PROTECTORS PER RULE 608.				Date: 03/03/2026

Paint

Condition	
Other (Content)	
Other (Capacity)	210 BBL
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	500 BBLs	STEEL AST		37.223021,-104.871544
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate

Comment:		
Corrective Action:		Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 263137 Type: WELL API Number: 071-07610 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 10/26/2015 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: FORM 4 BRHD SUNDRY #2319092

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 275633 Type: WELL API Number: 071-08291 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 10/26/2015 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: FORM 4 BRHD SUNDRY #2319093

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary Date: 2/19/2026 Time: 14:25 Operator: EVERGREEN NATURAL RESOURCES LLC 10705 Location: PIONEER 34-27 & TR API# 05-071-07617 County: Las Animas County. While there, I ECMC staff performed a field audit of the scout card, related documents and the location. During the audit the following possible compliance issues were observed: TRASH, RULE 606, 2/25/2026. TANK SIGN, RULE 605, 3/3/2026. BIRD PROTECTOR, 608, 3/3/2026. A follow-up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p>	beardslt	02/19/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404551425	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7455687
716302001	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7455685