

OIL AND GAS CONSERVATION COMMISSION OF THE STATE OF COLORADO

File in duplicate for Patented and Federal lands. File in triplicate for State lands.

RECEIVED

NOV 30 1967



COLORADO OIL & GAS CONSERVATION COMMISSION

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

Form fields 1-15: 1. OIL WELL [] GAS WELL [] OTHER Water Injection Well; 2. NAME OF OPERATOR PAT'S POWER TONGS, INC.; 3. ADDRESS OF OPERATOR Box 702, Grand Junction, Colorado 81501; 4. LOCATION OF WELL G W/2 Lot 7, Sec. 5; 5. LEASE DESIGNATION AND SERIAL NO. 00751824; 6. IF INDIAN, ALLOTTEE OR TRIBE NAME; 7. UNIT AGREEMENT NAME Liberty "J" Sand; 8. FARM OR LEASE NAME S. L. Mallo; 9. WELL NO. 4; 10. FIELD AND POOL, OR WILDCAT Liberty; 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 5, T.8N., R.54W.; 12. COUNTY OR PARISH Logan; 13. STATE Colo.; 14. PERMIT NO.; 15. ELEVATIONS 4380' G.L.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

Checkboxes for NOTICE OF INTENTION TO: TEST WATER SHUT-OFF, FRACTURE TREAT, SHOOT OR ACIDIZE, REPAIR WELL, PULL OR ALTER CASING, MULTIPLE COMPLETE, ABANDON, CHANGE PLANS; and SUBSEQUENT REPORT OF: WATER SHUT-OFF, FRACTURE TREATMENT, SHOOTING OR ACIDIZING, REPAIRING WELL, ALTERING CASING, ABANDONMENT. Includes note: (NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

This well is now known as LU-I-3 and has been purchased by the above designated company for salvage. It will be plugged and abandoned as follows:

Spot 15 sack plug in 5 1/2" casing from 5230' to 5361' covering perforations 5303 to 5312. Bradenhead squeeze.

Shoot off 5 1/2" casing.

Fill hole with mud and spot 10 sx. plug from 189' to 220' over base of surface casing at 201' depth.

Spot 5 sack plug at top of surface to bottom of cellar.

Weld on steel plate to top of surface at base of cellar.

Fill cellar with earth, rock and top off with top soil.

Table with 2 columns and 5 rows: DVR, FJP, HMM, JAM, JJD. Checkmarks are present in the second column for FJP, HMM, JAM, and JJD.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Agent/Pat's Power Tongs DATE 11-29-67

(This space for Federal or State office use)

APPROVED BY [Signature] TITLE Director DATE DEC 5 1967

CONDITIONS OF APPROVAL, IF ANY:

