

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404565561

Date Received:  
03/04/2026

**FIR RESOLUTION FORM**

**Overall Status:**

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 10840  
Name of Operator: ABUNDANCE ENERGY SERVICES LLC  
Address: 2121 S COLUMBIA AVE SUITE 101  
City: TULSA State: OK Zip: 74114

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
		<u>sjbcompliance@abundance-energy.com</u>

**ECMC INSPECTION SUMMARY:**

FIR Document Number: 714003425  
Inspection Date: 02/03/2026 FIR Submit Date: 02/04/2026 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: ABUNDANCE ENERGY SERVICES LLC Company Number: 10840  
Address: 2121 S COLUMBIA AVE SUITE 101  
City: TULSA State: OK Zip: 74114

LOCATION - Location ID: 326352

Location Name: HERRERA GAS UNIT A-N33N8W Number: 20NENW County: \_\_\_\_\_  
Qtrqr: NENW Sec: 20 Twp: 33N Range: 8W Meridian: N  
Latitude: 37.093120 Longitude: -107.745160

FACILITY - API Number: 05-067-00 Facility ID: 326352

Facility Name: HERRERA GAS UNIT A-N33N8W Number: 20NENW  
Qtrqr: NENW Sec: 20 Twp: 33N Range: 8W Meridian: N  
Latitude: 37.093120 Longitude: -107.745160

CORRECTIVE ACTIONS:

**1** CA# 210782

Corrective Action: Install new label per rule 605.h. Date: 03/04/2026

Response: CA COMPLETED Date of Completion: 02/06/2026

Operator Comment: New NFPA labels were installed on both tanks on 2/6/2026.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

2 CA# 210783

Corrective Action: Comply with rule 1002f.

Date: \_\_\_\_\_

Response: CA COMPLETED

Date of Completion: 03/02/2026

Operator Comment: The Gully erosion on the southern cut slope has been repaired and seeded. BMP's were used to mitigate its return in the future. All rutting on the location has also been repaired.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Attached find remedial report.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jaime Pugh

Signed: \_\_\_\_\_

Title: Engineering Analyst

Date: 3/4/2026 8:31:34 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404565561	FIR RESOLUTION SUBMITTED
404565589	Remedial Report

Total Attach: 2 Files