

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/15/2026

Submitted Date:

01/27/2026

Document Number:

717900365

**FIELD INSPECTION FORM**

Loc ID 332647 Inspector Name: Robinson, Taylor On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 69175  
Name of Operator: PDC ENERGY INC  
Address: 1099 18TH STREET SUITE 1500  
City: DENVER State: CO Zip: 80202

**Findings:**

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	

**General Comment:**

This is an environmental inspection for Location ID 332647 Stugart State Facility. Any corrective actions from previous inspections that have not been addressed are still applicable. There were several contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment: This inspection was in response to a recent spill. Spill ID 492647. The spill has been contained and clean up operations were underway at the time of the inspections. ECMC spoke with some of the environmental crew on site about the plan for sampling etc. A follow up inspection to track progress will be needed.

Multiple Spills and Releases?

**Fencing/:**

Type			
Comment:	<span style="color: blue;">The open excavation appeared to be within containment and there was orange construction fencing surrounding the open excavation. It appeared to be functioning properly.</span>		
Corrective Action:			Date: _____

**Venting:**

Yes/No			
Comment:			
Corrective Action:			Date: _____

**Flaring:**

Type			
Comment:			
Corrective Action:			Date: _____

**Location Construction**

Location ID: 332647 CDP: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Form 2A COAs:**

**Comment:**

Corrective Action:

Date: \_\_\_\_\_

**Wildlife BMPs:**

**Comment:**

Corrective Action:

Date: \_\_\_\_\_

**Comment:**

**Corrective Action:**

Date: 02/10/2026

**On Site Inspection (305):**

Surface Owner Contact Information:

Name: \_\_\_\_\_ Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_ Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_ Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: This inspection was in response to Spill ID 492647. It occurred within containment and clean up is ongoing.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**ECMC Comments**

Comment	User	Date
Approximately 10 BBL of crude oil overflowed out of a partially buried pit inside containment. The release is controlled and the facility has been shut in. Investigation and clean up activities are underway. A form 19 will be submitted within 72 hours of the release occurring.	robinsotl	01/27/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717900366	photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7475089">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7475089</a>