

Oxy COA Operations Summary

Well:	OLSON 1-X		Spud Date:	
Project:	COLORADO - WELD		Site:	T04N-R68W-S34
Event:	ABANDONMENT		Rig Name:	RANGER 5014
Start Date:	2/2/26		End Date:	2/24/26
Datum:	Ground Level @ 5145		Well UWI:	0512306144
Department		Approved By		Date Approved
05123061440000		JARROD BISHOP		02/24/2026
1/12/26				
Time From	Subcode	Subcode Description	Operation	
	Signs Posted	Signs Posted for Neighborhoods	INFORMATION SIGNS POSTED IN REQUESTED AREAS THROUGHOUT P&A OPERATIONS 01/12/2026	
	Form 42 Submit	Form 42 Submit with 48 Hours Notice	FORM 42 APROPED 01/08/2026 TO START OPS 1/11/2026. MIRU 01/11/2026	
1/16/26				
Time From	Subcode	Subcode Description	Operation	
	Plug Tag Requirement	Plug Tag Requirement	NO TAG NEEDED, PUMP CEMENT TO SURFACE	
	All Plugs Pumped	All Plugs Pumped were a Minimum of 100' Long	ALL PLUSG ARE 100' LONG	
1/28/26				
Time From	Subcode	Subcode Description	Operation	
8:00	Form 42 Submit	Form 42 Submit with 48 Hours Notice	FORM 42 NOTICE SENT ON 1/28/2026 FORM 2/2/2026	
2/23/26				
Time From	Subcode	Subcode Description	Operation	
11:30	Verify No Migration	Verify No Migration Before SC Shoe Plug	COA: COA: VERIFY THAT ALL PRESSURE AND FLUID MIGRATION HAS BEEN ELIMINATED PRIOR TO PLACING THE SC SHOE PLUG, VERIFIED THAT ALL PRESSURE GAS BEEN ELIMINATED	
2/24/26				
Time From	Subcode	Subcode Description	Operation	
6:30	Plug Tag Requirement	Plug Tag Requirement	COA: RIH & TAG TOC @ 13', L/D TBG, NOTIFY OXY OFFICE OF TAG DEPTH	