

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404582821

Date Received:
03/18/2026

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

0 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 24500

Name of Operator: PADCO LLC

Address: 1717 E VISTA CHINO A7-633

City: PALM SPRINGS State: CA Zip: 92262

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>BROTHERTON, ANDREA</u>		<u>abrotherton@136elcamino.com</u>
<u>Dan Richmond</u>	<u>918-630-9912</u>	<u>dan@dsrinc.net</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 720300062

Inspection Date: 01/06/2026

FIR Submit Date: 02/12/2026

FIR Status: _____

Inspected Operator Information:

Company Name: PADCO LLC

Company Number: 24500

Address: 1717 E VISTA CHINO A7-633

City: PALM SPRINGS State: CA Zip: 92262

LOCATION - Location ID: 393797

Location Name: STATE-62N58W Number: 36NENE County: _____

Qtrqtr: NENE Sec: 36 Twp: 2N Range: 58W Meridian: 6

Latitude: 40.099023 Longitude: -103.812409

FACILITY - API Number: 05-087- -00 Facility ID: 393797

Facility Name: STATE-62N58W Number: 36NENE

Qtrqtr: NENE Sec: 36 Twp: 2N Range: 58W Meridian: 6

Latitude: 40.099023 Longitude: -103.812409

CORRECTIVE ACTIONS:

1 CA# 210957

Corrective Action: Comply with the reclamation rules to remove all abandoned gathering line risers, flowline risers, and equipment (regardless of ownership). Cover the wellbore to protect livestock and wildlife.

Date: 05/12/2026

Response: OTHER

Operator Comment: Location is not owned or operated by PADCO LLC; gathering line risers, flowline risers and any other equipment on site are not/were not owned by PADCO LLC

ECMC Decision: _____

ECMC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: PADCO LLC respectfully asserts that it is not the owner or operator of this well. The State 1 well was plugged in 1971 and at no point was this well, or liability therefor, transferred to PADCO LLC (which was formed in 2003) from the previous owner/operator. Further, a 2004 field inspection by Mr. Kevin Lively of the COGCC found the well and site to comply with the rules at the time with specific regard to the flowlines, risers, etc. and which were identified as a separate facility owned and operated by the same gatherer/purchaser of the producing wells in the Adena Field. As such, even were PADCO LLC responsible for the State 1 well (which it is not), it would not be the responsible party for any legacy mid-stream equipment identified in the inspection. Finally, as the State 1 well was never assigned to PADCO LLC, either through a real property assignment or in the ECMC records, PADCO LLC has no rights, past or present, to enter the land upon which this well is located. PADCO LLC respectfully declines responsibility for any corrective actions associated with the State 1 well or the facilities/equipment discovered near this former well.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Dan Richmond

Signed: _____

Title: Field Operations Super

Date: 3/18/2026 1:02:05 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
404582821	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files