

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL RG #22-16-298 PAD

Location ID: 316517

Date: 03/17/2026



Photo # 3283 Entrance to location



Photo # 3313 API number & quarter-quarter section information is becoming illegible

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL RG #22-16-298 PAD

Location ID: 316517

Date: 03/17/2026



Photo # 3312 Location



Photo # 3322 NE corner of location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL RG #22-16-298 PAD

Location ID: 316517

Date: 03/17/2026



Photo # 3323 NW corner of location



Photo # 3324 SW corner of location

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL RG #22-16-298 PAD

Location ID: 316517

Date: 03/17/2026



Photo # 3325 SE corner of location



Photo # 3301 Failure to maintain chemical BMP/chemical containment approximately 3/4th full of fluid/not sufficient to contain possible spill

Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL RG #22-16-298 PAD

Location ID: 316517

Date: 03/17/2026



Photo # 3297 Failure to maintain chemical BMP/chemical containment approximately 3/4th full of fluid/not sufficient to contain possible spill



Photo # 3311 Methanol tank label is damaged/weathered, lacks required information