

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404591833

Date Received:  
03/23/2026

**FIR RESOLUTION FORM**

**Overall Status:**

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 10758  
Name of Operator: OGRIS OPERATING LLC  
Address: PO BOX 53467  
City: MIDLAND State: TX Zip: 79710

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>ZECHES. GIENA</u>	<u>7192204041</u>	<u>gzeches@ogrisop.com</u>
<u>BACA. DAVE</u>	<u>719-859-4066</u>	<u>dbaca@ogrisop.com</u>

**ECMC INSPECTION SUMMARY:**

FIR Document Number: 716302052  
Inspection Date: 03/18/2026 FIR Submit Date: 03/18/2026 FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: OGRIS OPERATING LLC Company Number: 10758  
Address: PO BOX 53467  
City: MIDLAND State: TX Zip: 79710

**LOCATION** - Location ID: 307896

Location Name: HILL RANCH-634S67W Number: 22NWSW County: LAS ANIMAS  
Qtrqtr: NWS Sec: 22 Twp: 34S Range: 67W Meridian: 6  
W  
Latitude: 37.066730 Longitude: -104.880610

**FACILITY** - API Number: 05-071- -00 Facility ID: 259238

Facility Name: HILL RANCH Number: 22-12 V  
Qtrqtr: NWS Sec: 22 Twp: 34S Range: 67W Meridian: 6  
W  
Latitude: 37.066730 Longitude: -104.880610

**CORRECTIVE ACTIONS:**

**1** CA# 211698

Corrective Action: Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002.,(2),D. THIS IS THE SECOND NOTICE FOR THIS CA, IMMEDIATE ACTION IS REQUIRED.

Date: \_\_\_\_\_

Response: CA COMPLETED Date of Completion: 03/20/2026

THE IMPACTED SOIL NEAR THE WELL HEAD HAS BEEN REMOVED AND REPLACED WITH FRESH PAD

Operator Comment: MATERIAL. ALL OPERATING EQUIPMENT HAS RECEIVED MECHANICAL INSPECTION/REPAIR AND THE HYDRAULIC HOSE CONNECTIONS HAVE BEEN REPLACED.

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

**2** CA# 211699

Corrective Action: INSTALL BIRD PROTECTOR SCREEN OR OTHER DEVICE TO PROTECT WILDLIFE PER RULE 608b.(7).

Date: 03/24/2026

Response: CA COMPLETED

Date of Completion: 03/20/2026

Operator Comment: THE TANK VENT HAS BEEN CAPPED.

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

**3** CA# 211700

Corrective Action: REMOVE UNUSED EQUIPMENT PER RULE 606.

Date: 03/24/2026

Response: CA COMPLETED

Date of Completion: 03/20/2026

Operator Comment: THE UNUSED EQUIPMENT HAS BEEN REMOVED FROM LOCATION. THE POLY PIPE ON THE EDGE OF THE PIT BERM IS IN USE.

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

OPERATOR COMMENT AND SUBMITTAL

Comment: ALL CORRECTIVE ACTIONS HAVE BEEN COMPLETED.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: GIENA ZECHES

Signed: \_\_\_\_\_

Title: ENVIRONMENTAL

Date: 3/23/2026 2:27:52 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404591833	FIR RESOLUTION SUBMITTED
404591856	PHOTO LOG

Total Attach: 2 Files