

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404593687

Date Received:
03/24/2026

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10844
Name of Operator: QB ENERGY OPERATING LLC
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Energy_QB</u>		<u>ecmc.inspections@qb-energy.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 701104614
Inspection Date: 03/16/2026 FIR Submit Date: 03/23/2026 FIR Status: _____

Inspected Operator Information:

Company Name: QB ENERGY OPERATING LLC Company Number: 10844
Address: 1001 17TH STREET SUITE 1600
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 334682

Location Name: Federal Number: 20-11 County: _____
(PN20)
Qtrqr: SESW Sec: 20 Twp: 7S Range: 95W Meridian: 6
Latitude: 39.418520 Longitude: -108.022280

FACILITY - API Number: 05-045- -00 Facility ID: 334682

Facility Name: Federal Number: 20-11
(PN20)
Qtrqr: SESW Sec: 20 Twp: 7S Range: 95W Meridian: 6
Latitude: 39.418520 Longitude: -108.022280

CORRECTIVE ACTIONS:

1 CA# 211770

Corrective Action: Repair or replace valve to be able to operate valve in emergency and normal operations. Comply with Rule 608.e. Date: 03/17/2026

Response: CA COMPLETED Date of Completion: 03/22/2026

Operator Comment: Replaced valve on inlet of separator to comply with ECMC Rule 608.e.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Joey Gracey

Signed: _____

Title: Compliance

Date: 3/24/2026 1:30:44 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
404593687	FIR RESOLUTION SUBMITTED
404593722	Separator Valve Replaced
404593725	Removed Bull plug
404593730	Tank Valve

Total Attach: 4 Files