

Inspection Photos  
Facility 5 Gas Line Spill  
Spill ID 492917



**Photo 1 – Small excavation on location. Impacts present in sidewall and free product on groundwater.**

**Photo 2 – Small excavation on location. Impacts present in sidewall and free product on groundwater.**

Inspection Photos  
Facility 5 Gas Line Spill  
Spill ID 492917



**Photo 3 – Hydrocarbon sheen observed on Big Dry Creek. Booms and mats placed in Big Dry Creek have not been maintained and require replacement.**



**Photo 4 – Hydrocarbon sheen observed on Big Dry Creek. Booms and mats placed in Big Dry Creek have not been maintained and require replacement.**

**Inspection Photos  
Facility 5 Gas Line Spill  
Spill ID 492917**



**Photo 5 - Operator equipment (hose, bucket, ect) remains on opposite bank of Big Dry Creek.**

**Photo 6 – Location photo. No operator personnel on location. Small excavation present adjacent to Big Dry Creek.**

**Inspection Photos  
Facility 5 Gas Line Spill  
Spill ID 492917**



**Photo 7 – Livestock present in area/adjacent to Big Dry Creek.**



**Photo 8 – Booms and mats placed in Big Dry Creek have not been maintained and are no longer effective in controlling the spread of impacts.**

Inspection Photos  
Facility 5 Gas Line Spill  
Spill ID 492917



**Photo 9 - Booms and mats placed in Big Dry Creek have not been maintained and require replacement.**



**Photo 10 – Hydrocarbon sheet observed when soils in Big Dry Creek were disturbed.**

Inspection Photos  
Facility 5 Gas Line Spill  
Spill ID 492917



**Photo 11 - Booms and mats placed in Big Dry Creek have not been maintained and require replacement.**

**Photo 12 – Booms and mats placed in Big Dry Creek have not been maintained and require replacement.**