

State of Colorado Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404598989

Date Received:
03/28/2026

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

0 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
.		cogccinspection@pdce.com
.		rbucogccinspectionreports@chevron.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708201910
Inspection Date: 01/07/2025 FIR Submit Date: 01/07/2025 FIR Status: _____

Inspected Operator Information:

Company Name: PDC ENERGY INC Company Number: 69175
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 464272

Location Name: BRIGGS-65N66W Number: 17SWSE County: _____
Qtrqtr: SWSE Sec: 17 Twp: 5N Range: 66W Meridian: 6
Latitude: 40.396020 Longitude: -104.803640

FACILITY - API Number: 05-123-00 Facility ID: 464272

Facility Name: BRIGGS-65N66W Number: 17SWSE
Qtrqtr: SWSE Sec: 17 Twp: 5N Range: 66W Meridian: 6
Latitude: 40.396020 Longitude: -104.803640

CORRECTIVE ACTIONS:

1 CA# 201522

Corrective Action: Perform reclamation activities in accordance with Rule 1004. Date: _____

Response: OTHER

Operator Comment: The entrance for oil and gas operations at the time was left in place for the gas gathering company to access their equipment after final reclamation activity had taken place. The gas gatherer did not originally respond to PDC's request to remove their equipment prior to decommissioning the location.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: The gas gathering company informed Chevron that the culvert in question was marked as City of Greeley infrastructure along with the next entrance/culvert to the north during the one call process. It appears the City of Greeley or CDOT is or was using the entrances to access and water the trees along the right of way. Several fiber optic communication cables have since been placed along the right of way paralleling the culverts along Highway 34 making removal of the infrastructure more critical working along the edge of a major highway.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jeff White

Signed: _____

Title: HSE

Date: 3/28/2026 9:53:20 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files