

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC LINDAUER MV 44-11 Pad
Location ID: 334949



**Location Overview: Location is within High
Priority/Density/Black Bear Habitat areas & in close proximity
to NSO Habitat area.**

Section/Township/Range: 11 7S96W

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC LINDAUER MV 44-11 Pad
Location ID: 334949

76° E
Garfield County




North West corner of location.

170° S
Garfield County



North East corner of location.

Garfield County



South West corner of location.

Garfield County



South East corner of location.