

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404516152

Date Received:
04/01/2026

FIR RESOLUTION FORM

Overall Status:

CA Summary:

6 of 6 CAs from the FIR responded to on this Form

6 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Popejoy, Dusty</u>		<u>dusty.popejoy@state.co.us</u>
<u>.TEP</u>		<u>COGCCInspectionReports@terraep.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 719500032
Inspection Date: 05/22/2025 FIR Submit Date: 06/04/2025 FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335089

Location Name: AP-66S96W Number: 14SWSE County: _____
Qtrqtr: SWSE Sec: 14 Twp: 6S Range: 96W Meridian: 6
Latitude: 39.516234 Longitude: -108.073651

FACILITY - API Number: 05-045- -00 Facility ID: 335089

Facility Name: AP-66S96W Number: 14SWSE
Qtrqtr: SWSE Sec: 14 Twp: 6S Range: 96W Meridian: 6
Latitude: 39.516234 Longitude: -108.073651

CORRECTIVE ACTIONS:

1 CA# 205297

Corrective Action: Install or repair liner material to ensure spill or released materials will be maintained with containment structure. Date: 07/05/2025

Response: CA COMPLETED Date of Completion: 09/11/2025

Operator Comment: Berm liner has been repaired. Corrective Action complete.

ECMC Decision: _____

ECMC
Representative:

2 CA# 205298

Corrective Action:

Date: 06/10/2025

Response: CA COMPLETED

Date of Completion: 09/11/2025

Operator Comment:

ECMC Decision: _____

ECMC
Representative:

3 CA# 205299

Corrective Action:

Date: 06/19/2025

Response: CA COMPLETED

Date of Completion: 09/11/2025

Operator Comment:

ECMC Decision: _____

ECMC
Representative:

4 CA# 205300

Corrective Action:

Date: 06/10/2025

Response: CA COMPLETED

Date of Completion: 09/11/2025

Operator Comment:

ECMC Decision: _____

ECMC
Representative:

5 CA# 205301

Corrective Action:

Date: 07/05/2025

Response: CA COMPLETED

Date of Completion: 09/11/2025

Operator Comment:

ECMC Decision: _____

ECMC
Representative:

6 CA# 205302

Corrective Action:

Date: 06/19/2025

Response: CA COMPLETED

Date of Completion: 09/11/2025

Operator Comment: Deadman has been removed. Corrective Action complete.

ECMC Decision: _____

ECMC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: CA#205297: Berm liner has been repaired. Corrective Action complete.
CA#205298: Load lines on tank manifold have been plugged to prevent wildlife entry. Corrective Action complete.
CA#205299: Wildlife egress has been installed at the wellhead cellar. Corrective Action complete.
CA#205300: Load hose has been removed from the tank containment. Corrective Action complete.
CA#205301: New wellhead signs have been hung. Corrective Action complete.
CA#205302: Deadman has been removed. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed: _____

Title: TEP Representative

Date: 4/1/2026 4:25:03 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number Description

404516152	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files