

## Inspection/Audit Photos

Location: KT RESOURCES LLC ANT HILL UNIT COUNTY #25-12 PAD

Location ID: 316336

Date: 03/26/2026



Photo # 3857 Entrance to location



Photo # 3890 Location - Operator name is starting to become illegible

## Inspection/Audit Photos

Location: KT RESOURCES LLC ANT HILL UNIT COUNTY #25-12 PAD

Location ID: 316336

Date: 03/26/2026



Photo # 3858 Location



Photo # 3865 Location

## Inspection/Audit Photos

Location: KT RESOURCES LLC ANT HILL UNIT COUNTY #25-12 PAD

Location ID: 316336

Date: 03/26/2026



Photo # 3888 Location



Photo # 3910 SE corner of location

## Inspection/Audit Photos

Location: KT RESOURCES LLC ANT HILL UNIT COUNTY #25-12 PAD

Location ID: 316336

Date: 03/26/2026



Photo # 3911 NE corner of location



Photo # 3912 NW corner of location

## Inspection/Audit Photos

Location: KT RESOURCES LLC ANT HILL UNIT COUNTY #25-12 PAD

Location ID: 316336

Date: 03/26/2026



Photo # 3914 SW corner of location



Photo # 3876 Stained soil beneath treater

## Inspection/Audit Photos

Location: KT RESOURCES LLC ANT HILL UNIT COUNTY #25-12 PAD

Location ID: 316336

Date: 03/26/2026



**Photo # 3877 Stained soil beneath treater**



**Photo # 3919 Failure to minimize erosion & transport of sediment off location/insufficient BMP's**

## Inspection/Audit Photos

Location: KT RESOURCES LLC ANT HILL UNIT COUNTY #25-12 PAD

Location ID: 316336

Date: 03/26/2026



**Photo # 3925 Failure to minimize erosion & transport of sediment off location/insufficient BMP's**