

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/08/2026

Submitted Date:

04/08/2026

Document Number:

715802175

FIELD INSPECTION FORM

Loc ID 320511 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 21 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272178	WELL	SI	01/01/2026	OW	001-09507	STANDLEY 2-2	SI
272179	WELL	PR	08/01/2024	GW	001-09506	STANDLEY 1-2	SI

General Comment:

[This is a field audit of the scout card, related documents and the location, due to a form 42\(LIQ\)-00 doc # 404608526 .](#)

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	adequate both need to be secured to the well the belong one is in the dirt by unused equipment the other is hanging on by a wire.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Good Housekeeping:			
Type	TRASH		
Comment:	Trash mixed in with dead vegetation/tumbleweeds		
Corrective Action:	Comply with rule 606	Date:	04/15/2026
Type	WEEDS		
Comment:	Dead vegetation/tumbleweeds around PR equipment fencing the tank battery fencing inside the TB fencing & TB equipment.		
Corrective Action:	Comply with rule 606	Date:	04/15/2026
Type	OTHER		
Comment:	Stained soil by the bradenhead valve needs to be cleaned & removed.		
Corrective Action:	Properly dispose of oily waste in accordance with 905.e	Date:	04/22/2026
Type	OTHER		
Comment:	Bradenhead valve need to be tightened to prevent stained soil.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.	Date:	04/22/2026

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No _____

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Chain link		
Corrective Action:		Date:	

Type	IGNITOR/COMBUSTOR		
Comment:	Chain link		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Fabricated steel pipe		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Shares with ignitor, Chain link.		
Corrective Action:		Date:	

Equipment:			corrective date
Type:	#		
Comment:	No change to equipment from previous FIR. Both Gas meter cards indicate current calibration.		
Corrective Action:		Date:	

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:	No change to equipment from previous FIR.				
Corrective Action:				Date:	

Paint	
Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:			Date:	

Venting:		
Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:	
Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 272178 Type: WELL API Number: 001-09507 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI since 1-2026

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 07/15/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 5 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: exposed at surface

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 272179 Type: WELL API Number: 001-09506 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI, valves are closed.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 06/12/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 5 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: exposed at surface

Corrective Action: _____ Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On Wednesday 4-8-2026 at approximately 1105 hrs. I, Inspector Robbie Revas, Conducted an audit of the well scout card & related forms followed by an onsite inspection: Inspection is due to a form 42(LIQ)-00 doc # 404608526. No KP Kauffman hands on locatin at the time of inspection. Operator: KP Kauffman Location # 320511 API # 05-001-09506 Well name: Standley 1-2 County: Adams Weather: Cloudy Temp: 70* Location: dry While there, I observed a wellsite & tank battery, SI at the time of inspection. During this inspection the following possible compliance issues were observed: 606 housekeeping: Dead vegetation & trash need to be removed from location. CA date 4-15-2026. 608.e Mech. conditions: Valves on both bradenheads need to be tightened to prevent stained soil. CA date 4-22-2026. 905.e housekeeping: oily waste by bradenhead valve needs to be cleaned & removed from location. CA date 4-22-2026. Any corrective actions from previous Inspections that have not been addressed are still applicable. See attached photos. A follow up on this site inspection will be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules.</p>	revasr	04/08/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715802176	Location photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7508944