



COLORADO

Energy & Carbon Management Commission

Department of Natural Resources

1120 Lincoln Street, Suite 801
Denver, CO 80203

www.colorado.gov/ecmc

WARNING LETTER # 404614836

04/10/2026

OGRIS OPERATING LLC (# 10758)

GIENA WARD

gward@ogrisop.com

PO BOX 53467

MIDLAND, TX 79710

GOLDEN EAGLE MINE F-2 (API# 071-06407)

NENW, 28, 33S, 67W, LAS ANIMAS

This Warning Letter is to inform you that OGRIS OPERATING LLC (“Operator”) may be in violation of the rules and regulations of the Colorado Energy and Carbon Management Commission (“ECMC”) and corrective action is required.

ECMC has reasonable cause to believe that Operator has committed one or more violations of the Oil and Gas Conservation Act, or of a rule, regulation, or order of the Commission, or of a permit issued by the Commission. Operator is required to comply with this Warning Letter by the **Corrective Action Deadline Date(s)** to resolve the alleged violation(s). Failure to do so will result in the issuance of a Notice of Alleged Violation and initiation of enforcement proceedings in which ECMC will seek monetary penalties for the alleged violations pursuant to § 34-60-121, C.R.S. and Rule 525, ECMC Rules of Practice and Procedure, 2 CCR 404-1.

Alleged Violation(s) and Required Corrective Action(s):

417 Mechanical Integrity Testing

Violation Date: 07/27/2012

Violation Discovery Date: 02/02/2026

Description of Alleged Violation: Operator is receiving this letter because, based on ECMC records, ECMC has reason to believe the Well(s) indicated above and/or in the attached table presents one or more compliance issues. Operator should review its records to verify if this is a shut-in (“SI”) or temporarily abandoned (“TA”) well past due for a Mechanical Integrity Test (“MIT”).

Pursuant to Rule 417.b., Operator is required to conduct an MIT on SI wells within two years of the initial shut-in date and then at five (5) year intervals after an initial successful MIT. ECMC Rules DO NOT permit placing a well back on production to fulfill, or in lieu of, the requirements to conduct an MIT. If the above referenced Well has been SI for over two years and Operator has not conducted an initial MIT or is SI and has not had an MIT for over five years after the initial MIT, then Operator is in violation of Rule 417.b.

Pursuant to Rule 417.c., Operator is required to conduct an MIT on TA wells within thirty (30) days of temporarily abandoning the well, and then at five (5) year intervals after an initial successful MIT. ECMC Rules DO NOT permit placing a well back on production to fulfill, or in lieu of, the requirements to conduct an MIT. If the above referenced Well has been TA for over thirty days and Operator has not conducted an initial MIT or is TA and has not had an MIT for over five years after the initial MIT, then



COLORADO

Energy & Carbon Management Commission

Department of Natural Resources

1120 Lincoln Street, Suite 801
Denver, CO 80203

www.colorado.gov/ecmc

Operator is in violation of Rule 417.c.

Pursuant to Rule 417.e., Operator is required to submit notice to the Director on a Form 42, Field Operations Notice - Mechanical Integrity Test ("MIT"), at least ten (10) days prior to conducting an MIT and submission of MIT results (successful or not) on a Form 21, within thirty (30) days after the test. If an MIT is not witnessed by ECMC staff, a pressure chart must accompany this Form 21 report.

Required Corrective Action: If the Well is SI or TA but Operator has not conducted a successful initial MIT or successful follow-up five year MIT, then Operator shall conduct a successful MIT on the Well or plug and abandon the Well.

Rule 405.n., requires notice to the Director on a Form 42, Field Operations Notice at least ten (10) days prior to conducting an MIT and Rule 418, requires submission of MIT results (successful or not) on a Form 21, within thirty (30) days after the test. If an MIT is not witnessed by ECMC staff, a pressure chart must accompany this Form 21 report.

If the Well lacks mechanical integrity, Rule 417.f. requires the Operator to make repairs or plug and abandon within the timeframe prescribed by Rule 417.f.

Rule 435 requires Operator to submit a Form 6, Notice of Intent to Abandon, and secure Director approval prior to plugging and abandonment of a well and to submit a Form 6, Subsequent Report of Abandonment, within 30 days after plugging and abandonment of the well has been completed.

Corrective Action Deadline Date: 07/10/2026

How to Comply with Warning Letter:

Operator shall complete the Required Corrective Action(s) above within the deadline(s) provided. Upon completion of the Corrective Action(s), Operator shall provide notice and evidence of completion to the ECMC staff identified below by the Corrective Action Deadline Date(s):

ECMC Representative: Greager, Meredith
Email: meredith.greager@state.co.us

Title: Engineering QA Specialist
Phone Num: (720) 830-4175x

If you have any questions about this Warning Letter, please contact the ECMC Representative identified above.

Failure to Comply with Warning Letter:

If Operator fails to perform Required Corrective Action(s) on or before the Corrective Action Deadline Date(s) stated above ECMC will issue a Notice of Alleged Violation and seek penalties pursuant to § 34-60-121, C.R.S. and Rule 525, ECMC Rules of Practice and Procedure, 2 CCR 404-1.

Disclaimers:

If the alleged violation(s) in this Warning Letter are the subject of previously issued Notice(s) of Alleged Violation ("NOAV") or Enforcement Order(s) ("Order"), Operator's obligations and the corrective actions and deadlines in such NOAV or Order stand and are not affected by this Warning Letter.

If issued in error, the Enforcement Unit reserves the right to rescind this Warning Letter prior to the ECMC Representative's receipt of Operator's notice and evidence of completion of the Corrective Action.



COLORADO

Energy & Carbon Management Commission

Department of Natural Resources

1120 Lincoln Street, Suite 801
Denver, CO 80203

www.colorado.gov/ecmc

All well data, rules and forms are available on our website at www.colorado.gov/ecmc.

Sincerely,

Greager, Meredith
Engineering QA Specialist

Attachments

View Attachments in Imaged Documents on ECOM website <http://ecmcweblink.state.co.us/> Search by Document Number.

Document Number	Description
------------------------	--------------------

404616023	WARNING LETTER DOCUMENTATION
-----------	------------------------------

Total Attach: 1 Files