

# State of Colorado Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404616465

Date Received:  
04/13/2026

## FIR RESOLUTION FORM

**Overall Status:**

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: <u>10705</u>	Contact Name and Telephone:
Name of Operator: <u>EVERGREEN NATURAL RESOURCES LLC</u>	Name: _____
Address: <u>1775 SHERMAN ST. #2775</u>	Phone: ( ) _____ Fax: ( ) _____
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80203</u>	Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Distribution, Evergreen</u>	<u>719-846-7898</u>	<u>cogcc.evergreen@enrllc.com</u>
<u>D DYKE, TRACY</u>	<u>719-846-7898</u>	<u>tracy.dyke@enrllc.com</u>

### ECMC INSPECTION SUMMARY:

FIR Document Number: 716302130

Inspection Date: 04/02/2026      FIR Submit Date: 04/02/2026      FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: EVERGREEN NATURAL RESOURCES LLC      Company Number: 10705

Address: 1775 SHERMAN ST. #2775

City: DENVER      State: CO      Zip: 80203

### LOCATION - Location ID: 309036

Location Name: BELARDE-631S66W      Number: 34SWNW      County: LAS ANIMAS

Qtrqtr: SWN      Sec: 34      Twp: 31S      Range: 66W      Meridian: 6

W

Latitude: 37.305130      Longitude: -104.775490

### FACILITY - API Number: 05-071-00      Facility ID: 287036

Facility Name: BELARDE      Number: 12-34

Qtrqtr: SWN      Sec: 34      Twp: 31S      Range: 66W      Meridian: 6

W

Latitude: 37.305130      Longitude: -104.775490

### CORRECTIVE ACTIONS:

<b>1</b> CA# 212069	
Corrective Action: <div style="border: 1px solid black; padding: 5px;">           Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002.,(2).D. THIS IS THE 3RD NOTICE FOR THIS CA. IT APPEARS THAT THE OTHER AREAS OF IMPACTED SOILS AROUND LOCATION HAVE BEEN ADDRESSED HOWEVER AROUND THE WELLHEAD IS GETTING WORSE THE LEAK MUST BE ADDRESSED IMMEDIATE ACTION IS REQUIRED.         </div>	Date: _____

Response: CA COMPLETED

Date of Completion: 04/10/2026

Operator Comment: Leak repairs and oil stain clean up per rule 1002(2)D

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

**OPERATOR COMMENT AND SUBMITTAL**

Comment: \_\_\_\_\_

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tracy Dyke

Signed: \_\_\_\_\_

Title: Construction Technician

Date: 4/13/2026 7:20:20 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

404616466	Leak repairs and oil clean up
-----------	-------------------------------

Total Attach: 1 Files