

## Tammy Jones

---

**From:** Jose Frias Hernandez  
**Sent:** Wednesday, April 15, 2026 2:04 PM  
**To:** Tammy Jones; Clint Calvert; Freddy Proctor; Jennifer Street; Priscilla Shorty; Shad Brown  
**Subject:** Re: SEVER 1 - INC - 714003536  
**Attachments:** Image.jpeg; Image.jpeg

Sever 1  
Complete on 4-9-26

Get [Outlook for iOS](#)

---

**From:** Tammy Jones <tajones@hilcorp.com>  
**Sent:** Wednesday, April 1, 2026 6:57:38 AM  
**To:** Jose Frias Hernandez <jfrias@hilcorp.com>; Clint Calvert <Clint.Calvert@hilcorp.com>; Freddy Proctor <fproctor@hilcorp.com>; Jennifer Street <jstreet@hilcorp.com>; Priscilla Shorty <pshorty@hilcorp.com>; Shad Brown <shbrown@hilcorp.com>; Tammy Jones <tajones@hilcorp.com>  
**Subject:** SEVER 1 - INC - 714003536

<b>Today's Date:</b>	4/1/2026					
<b>Well Name:</b>	SEVER 1	<b>Location:</b>	Sec: 13	Twn: 032N	Rng: 010W	UL: H
<b>API Number:</b>	05.067.05082	<b>Footage:</b>	1650' FNL & 990' FEL			
<b>Operator:</b>	Hilcorp Energy Company	<b>Area/Run/MSO:</b>	01	0105	Pepe Frias Hernandez	
<b>Meter #:</b>	1920101		<b>Pipeline:</b>	RC		
<b>INC Number:</b>	714003536	<b>Agency:</b>	ECMC	<b>Inspector:</b>	Corey Mcdonough	

Type of INC:	Written	Photos Required:	Yes	Due Date:	8/30/2024
Issue of Concern:	<b>Comment:</b> Inspection doc #714001069 observed erosion issues along the access road and required compliance by 8/30/2024. It was observed in this inspection that erosion and rutting issues persist on the road. Original CA has not been addressed. Original CA and date remains applicable. <b>Corrective Action: Comply with rule 1002f.</b>				

Thanks,

*Tammy Jones* | HILCORP ENERGY COMPANY | San Juan Regulatory | 505.324.5185 | [tajones@hilcorp.com](mailto:tajones@hilcorp.com)

