

Storm Water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS SG 13-26 Pad

Location ID: 334393



Location Overview: Location is within High Priority/Density/Black Bear Habitat areas/Bald Eagle Roost Sites & in close proximity to NSO Habitat area/Bald Eagle Nest Site. Location is in close proximity to Rule 411b Generalized Intermediate & External Buffers. Location is approximately 496 yards from the Colorado River.

Section/Township/Range: 26 7S96W



Storm water Management and Erosion control

Location Name: TEP ROCKY MOUNTAIN LLC SPECIALTY RESTAURANTS SG 13-26 Pad

Location ID: 334393

123° SE
Garfield County



North West corner of location.

217° SW
Garfield County



North East corner of location.

Garfield County



South West corner of location.

Garfield County



South East corner of location.