

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404625822

Date Received:
04/20/2026

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 4 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
.		mark.schlagenhauf@state.co.us
<u>Inspection, Terra TEP</u>	<u>970-285-9377</u>	ECMCInspectionReports@flywheelenergy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 701104673
Inspection Date: 04/02/2026 FIR Submit Date: 04/09/2026 FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 323901

Location Name: Savage Number: RMV 15-35 County: _____
Qtrqtr: SWN Sec: 35 Twp: 6S Range: 94W Meridian: 6
W
Latitude: 39.483297 Longitude: -107.862906

FACILITY - API Number: 05-045- -00 Facility ID: 323901

Facility Name: Savage Number: RMV 15-35
Qtrqtr: SWN Sec: 35 Twp: 6S Range: 94W Meridian: 6
W
Latitude: 39.483297 Longitude: -107.862906

CORRECTIVE ACTIONS:

1 CA# 212183

Corrective Action: Comply with Rule 1002.f(2).B. Date: 04/25/2026

Response: CA COMPLETED Date of Completion: 04/15/2026

Operator Comment: Plugs were installed on glycol vessel valves. Corrective Action complete.

ECMC Decision: _____

ECMC Representative: _____

2 CA# 212184

Corrective Action: Inspect shut in flowline and apply OOSLAT
Comply with Rule 1101.a.(3).C..

Date: 05/09/2026

Response: CA COMPLETED

Date of Completion: 04/15/2026

Operator Comment: Lock has been installed on flowline. Corrective Action complete.

ECMC Decision: _____

ECMC Representative: _____

4 CA# 212186

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 04/25/2026

Response: CA COMPLETED

Date of Completion: 04/15/2026

Operator Comment: Corroded valve on the separator riser manifold was replace. Corrective Action complete.

ECMC Decision: _____

ECMC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: CA #212183: Plugs were installed on glycol vessel valves. Corrective Action complete.
CA #212184: Lock has been installed on flowline. Corrective Action complete.
CA #212186: Corroded valve on the separator riser manifold was replace. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed: _____

Title: TEP Representative

Date: 4/20/2026 7:52:01 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
404625822	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files