

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/13/2026

Submitted Date:

04/14/2026

Document Number:

713401353

FIELD INSPECTION FORM

Loc ID 315114 Inspector Name: Popejoy, Dusty On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10539
Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP
Address: 734 MAIN STREET 3RD FLOOR
City: GRAND JUNCTION State: CO Zip: 81501

Findings:

- 11 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Katz, Aaron		aaron.katz@state.co.us	
Haverkamp, Curtis		curtis.haverkamp@state.co.us	
GAS, UTAH		inspections@utahgascorp.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230276	WELL	SI	05/01/2024	OW	103-07935	GOVERNMENT 6-2X	SI

General Comment:

[Witnessed Alternative Bradenhead Test](#)

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	OTHER		
Comment:	Sign at pump jack		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	970-693-6021/911		
Corrective Action:		Date:	
Good Housekeeping:			
Type	OTHER		
Comment:	A minor release was observed during Bradenhead testing. Operator immediately conducted cleanup and removed impacted material. The condition was corrected at the time of inspection.		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:			
Corrective Action:		Date:	
Equipment:			
Type: Other	# 1		corrective date
Comment:	Backhoe		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead valve is accessible/equipped with gauge		
Corrective Action:		Date:	
Type: Pump Jack	# 1		

Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Water truck		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 230276 Type: WELL API Number: 103-07935 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Shut in - Last produced April 2024

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 07/09/2025 Annual Brhd Completed? _____

Last Brhd Test Results Initial Surf Csg Pressure: 133 Fluid Type: NONE

End Surf Csg Pressure: 6

Comment: Witnessed Alternative Bradenhead Test
Refer to Document Numbers 404597680 & 404604290
BH pressure at start of test - 179 psi
Tubing pressure at start of test - 3 psi
Casing pressure at start of test - 484 psi
BH pressure at end of test - 3 psi
Tubing pressure at end of test - 3 psi
Casing pressure at end of test - 334 psi
Bradenhead Fluid - Yes
150 psi (31%) pressure drop on the PC during the BH test

10/14/2026

Corrective Action: Comply with CECMC Rule 417 (f)

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Alternative Bradenhead Test](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary</p> <p>On 04/13/2026 at approximately 8:02 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection/audit at UTAH GAS OP LTD DBA UTAH GAS CORP GOVERNMENT #6-2X at Location ID #315114 in Rio Blanco County, Colorado.</p> <p>This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority, NSO, Density Habitat regulations.</p> <p>While there, I Witnessed Alternative Bradenhead Test.</p> <p>During the inspection/audit, the following compliance issues were observed:</p> <p>1. Inspected Facilities - 150 psi (31%) pressure drop on the PC during the BH test/not in compliance with CECMC rules with a CA date of 10/14/2026</p> <p>A follow-up on this site inspection/audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p> <p>This is a summary of inspection/audit report.</p>	popejoyd	04/13/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404620069	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7514542
713401354	713401353 Inspection-Audit Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7514541