

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/21/2026

Submitted Date:

04/21/2026

Document Number:

714202766

FIELD INSPECTION FORM

Loc ID 457362 Inspector Name: Santistevan, Brittani On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10821
Name of Operator: 1876 RESOURCES LLC
Address: 1700 LINCOLN ST, STE4800
City: DENVER State: CO Zip: 80203

Findings:

- 9 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Sokolowski, Ryan	(574) 360-7168	ryan.sokolowski@1876resources.com	Regulatory Manager
McCormick, Connor	(303) 968-7383	Connor.mccormick@1876resources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
481785	TANK BATTERY	AC	03/22/2022		-	Knight Pad Tank Battery	AC

General Comment:

This is an audit of KNIGHT PAD scout card and related documents followed by a field inspection.

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:			Date:
Type	BATTERY		
Comment:	Adequate		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	One tank is missing an NFPA placard. See attached photo.		
Corrective Action:	Install sign to comply with Rule 605.h.		Date: 05/21/2026

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	sound wall west of location and north. See attached photos.		
Corrective Action:			Date:

Equipment:			corrective date
Type: Vertical Heated Separator	#		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 12		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 12		
Comment:			
Corrective Action:			Date:
Type: LACT	# 1		

Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 7		
Comment:			
Corrective Action:			Date:
Type: Compressor	# 3		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 5		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	OTHER	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	330 BBLs	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	OTHER	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	330 BBLs	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:	Shares containment with other tanks.			
Corrective Action:			Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 481785 Type: TANK API Number: - Status: AC Insp. Status: AC

Producing Well

Comment:	PR; pilot light appears to be ignited in ECD.	
Corrective Action:		Date:

ECMC Comments

Comment	User	Date
<p>ECMC Audit Report Summary WEATHER CONDITIONS: sunny, dry ground. On Tuesday, April 21, 2026 at approximately 1045, I, Inspector Brittani Santistevan, conducted an on-site inspection at KNIGHT PAD (1876 Resources LLC), at location ID: 481785 in WELD COUNTY, Colorado. While there, I observed a producing facility. During this inspection the following possible compliance issues were observed: 1. It appears to be no NFPA placard displayed on one tank. Install sign to comply with Rule 605.h. (Corrective Action Date: May 21, 2026) See attached photo #6.</p> <p>A follow up on this site audit needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules. This is a summary of the audit report.</p>	santistb	04/21/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
714202767	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7522658