

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/23/2026

Submitted Date:

04/23/2026

Document Number:

713401384

**FIELD INSPECTION FORM**

Loc ID 485795 Inspector Name: Popejoy, Dusty On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 10844  
Name of Operator: QB ENERGY OPERATING LLC  
Address: 1001 17TH STREET SUITE 1600  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 10 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name   | Phone | Email                          | Comment |
|----------------|-------|--------------------------------|---------|
| ENERGY, QB     |       | ecmc.inspections@qb-energy.com |         |
| Wilson, Justin |       | jrwilson@blm.gov               |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name              | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------------|-------------|
| 486809      | WELL | DG     | 04/18/2026  |            | 103-12690 | RNPU B27 FED 14C-22<br>197 | DG          |

**General Comment:**

This is a Field Inspection/audit of the scout card, related documents and the location.  
While there, I observed Drilling operations on location.

**Location**

|                    |        |       |  |
|--------------------|--------|-------|--|
| <b>Lease Road:</b> |        |       |  |
| Type               | Access |       |  |
| comment:           | Access |       |  |
| Corrective ActionL |        | Date: |  |

Overall Good:

|                      |   |       |            |
|----------------------|---|-------|------------|
| <b>Signs/Marker:</b> |   |       |            |
| Type                 | OTHER   |       |            |
| Comment:             | Location sign lying on the ground with incorrect operator name and no location ID number. Informed consultant Scotty Bauman and he reinstalled sign and informed me they would update signage. Refer to photos                |       |            |
| Corrective Action:   | Comply with CECMC rule 605  | Date: | 04/30/2026 |
| Type                 | DRILLING/RECOMP   |       |            |
| Comment:             | No rig sign at intersection along lease road.<br><br>Informed consultant Scotty Bauman and issued immediate corrective action on observed compliance issue and he immediately installed sign at intersection. Refer to photos |       |            |
| Corrective Action:   | Comply with CECMC rule 605  | Date: | 04/23/2026 |

|                                  |                  |             |
|----------------------------------|------------------|-------------|
| <b>Emergency Contact Number:</b> |                  |             |
| Comment:                         | 970-285-2615/911 |             |
| Corrective Action:               |                  | Date: _____ |

Overall Good:

| <b>Spills:</b> |      |        |  |
|----------------|------|--------|--|
| Type           | Area | Volume |  |

In Containment: No

Comment:

Multiple Spills and Releases?

|                    |   |       |                 |
|--------------------|---|-------|-----------------|
| <b>Equipment:</b>  |   |       | corrective date |
| Type: Other        | # 1                                     |       |                 |
| Comment:           | Drilling Rig & all associated equipment |       |                 |
| Corrective Action: |   | Date: |                 |

|                    |    |       |  |
|--------------------|----|-------|--|
| <b>Venting:</b>    |    |       |  |
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| <b>Flaring:</b>    |  |       |  |
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Inspected Facilities**

Facility ID: 486809 Type: WELL API Number: 103-12690 Status: DG Insp. Status: DG

**Well Drilling**

**Rig:** Rig Name: NABORS B04 Pusher/Rig Manager: \_\_\_\_\_  
Permit Posted: SATISFACTORY Access Sign: ACTION REQUIRED

**Well Control Equipment:**

Pipe Ram: \_\_\_\_\_ Blind Ram: \_\_\_\_\_ Hydril Type: \_\_\_\_\_  
Pressure Test BOP: \_\_\_\_\_ Test Pressure PSI: \_\_\_\_\_ Safety Plan: \_\_\_\_\_

**Drill Fluids**

**Management:**

Lined Pit: \_\_\_\_\_ Unlined Pit: \_\_\_\_\_ Closed Loop: YES Semi-Closed Loop: \_\_\_\_\_  
Multi-Well: \_\_\_\_\_ Disposal Location: \_\_\_\_\_

**Comment:** On 04/23/2026 at approximately 13:15 hours I observed drilling operations drilling production.  
Refer to document numbers 404625673, 404625674 and 404625675

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms            |                 |                         |                       |               |                          |         |
|                  |                 | Ditches                 |                       |               |                          |         |
| Gravel           |                 |                         |                       |               |                          | Sparse  |
|                  |                 | Culverts                |                       |               |                          |         |
| Compaction       |                 |                         |                       |               |                          |         |
| Ditches          |                 |                         |                       |               |                          |         |
|                  |                 | Compaction              |                       |               |                          |         |
|                  |                 | Gravel                  |                       |               |                          |         |
|                  |                 | Sediment Traps          |                       |               |                          |         |

Comment: Operator is responsible for maintaining Best Management Practices (BMP's) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

| Comment   | User     | Date       |
|---|----------|------------|
| <p><a href="#">CECMC Inspection/Audit Report Summary</a></p> <p>On 04/23/2026 at approximately 12:55 hours, Compliance Inspector Dusty Popejoy conducted an on-site inspection/audit at QB ENERGY OPERATING LLC RNPU B27 FED #14C-22 197 at Location ID #485795 in Rio Blanco County, Colorado.</p> <p>This location is within or in close proximity to a Parks and Wildlife (CPW) District with High Priority, NSO, Density Habitat regulations.</p> <p>While there, I observed Drilling operations on location.</p> <p>During the inspection/audit, the following compliance issues were observed:</p> <ol style="list-style-type: none"> <li>1. Signs/Marker - No rig sign at intersection along lease road with a CA date of 04/23/2026</li> <li>2. Signs/Marker - Location sign lying on the ground with incorrect operator name and no location ID number with a CA date of 04/30/2026</li> </ol> <p>A follow-up on this site inspection/audit will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.</p> <p>This is a summary of inspection/audit report.</p> | popejoyd | 04/23/2026 |

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 404632852    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7525653">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7525653</a> |

|           |                                   |   |
|-----------|-----------------------------------|---|
| 713401385 | 713401384 Inspection-Audit Photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7525652">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7525652</a> |
|-----------|-----------------------------------|---|