

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404635562

Date Received:  
04/30/2026

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 4 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10775

Name of Operator: KT RESOURCES LLC

Address: 3381 WESTBROOK LANE

City: HIGHLANDS RANCH State: CO Zip: 80129

Contact Name and Telephone:

Name:

Phone: ( ) Fax: ( )

Email:

Additional Operator Contact:

Contact Name	Phone	Email
Baumgras, Dan		Dan@KT-Res.com
Gale, Tony	(303) 886-8733	tony@kt-res.com
Adams, Karen	(303) 886-8733	adams@kt-res.com
Kellerby, Shaun	(970) 712-1248	shaun.kellerby@state.co.us
Katz, Aaron	(970) 765-6300	aaron.katz@state.co.us

ECMC INSPECTION SUMMARY:

FIR Document Number: 702501170

Inspection Date: 04/20/2023 FIR Submit Date: 04/21/2023 FIR Status:

Inspected Operator Information:

Company Name: KT RESOURCES LLC Company Number: 10775

Address: 3381 WESTBROOK LANE

City: HIGHLANDS RANCH State: CO Zip: 80129

LOCATION - Location ID: 315978

Location Name: MOBIL-JACOBS-61N97W Number: 1NESW County: RIO BLANCO

Qtrqr: NESW Sec: 1 Twp: 1N Range: 97W Meridian: 6

Latitude: 40.082969 Longitude: -108.230001

FACILITY - API Number: 05-103-00 Facility ID: 231846

Facility Name: MOBIL-JACOBS Number: 1-3

Qtrqr: NESW Sec: 1 Twp: 1N Range: 97W Meridian: 6

Latitude: 40.082969 Longitude: -108.230001

CORRECTIVE ACTIONS:

1 CA# 169926

Corrective Action: The Operator will conspicuously post and maintain the date of the last meter calibration in a legible condition at each meter at all times.

Date: 05/08/2023

Response: CA COMPLETED

Date of Completion: 03/06/2025

Operator Comment: Per inspection 715501392 at this location, dated 3/6/2025, this corrective action has been resolved.

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

**3** CA# 169929

Corrective Action: Provide proper BMPs to prevent sediment migration from location and lease road.

Date: 05/08/2023

Response: CA COMPLETED

Date of Completion: 03/06/2025

Operator Comment: Per inspection 715501392 at this location, dated 3/6/2025, this corrective action has been resolved.

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

**4** CA# 170284

Corrective Action: Perform successful mechanical integrity test. If a successful MIT cannot be performed within 30 day CA time the well must be plugged within 3 months.

Date: 05/21/2023

Response: CA COMPLETED

Date of Completion: 03/06/2025

Operator Comment: Per inspection 715501392 at this location, dated 3/6/2025, this corrective action has been resolved.

ECMC Decision: \_\_\_\_\_

ECMC Representative: \_\_\_\_\_

**OPERATOR COMMENT AND SUBMITTAL**

Comment: \_\_\_\_\_

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Amber Barnett

Signed: \_\_\_\_\_

Title: Compliance Specialist

Date: 4/30/2026 11:51:57 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<b>Document Number</b>	<b>Description</b>
404635562	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files