

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404635580

Date Received:
04/30/2026

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 3 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10775

Name of Operator: KT RESOURCES LLC

Address: 3381 WESTBROOK LANE

City: HIGHLANDS RANCH State: CO Zip: 80129

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Wilson, Justin</u>	<u>(970) 878-3825</u>	<u>jrwilson@blm.gov</u>
<u>Adams, Karen</u>	<u>(303) 886-8733</u>	<u>adams@kt-res.com</u>
<u>Gale, Tony</u>	<u>(303) 886-8733</u>	<u>tony@kt-res.com</u>
<u>Baumgras, Dan</u>	<u>(307) 321-3299</u>	<u>Dan@KT-Res.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 702502325

Inspection Date: 01/30/2024

FIR Submit Date: 01/30/2024

FIR Status: _____

Inspected Operator Information:

Company Name: KT RESOURCES LLC

Company Number: 10775

Address: 3381 WESTBROOK LANE

City: HIGHLANDS RANCH State: CO Zip: 80129

LOCATION - Location ID: 315978

Location Name: MOBIL-JACOBS-61N97W Number: 1NESW County: RIO BLANCO

Qtrqtr: NESW Sec: 1 Twp: 1N Range: 97W Meridian: 6

Latitude: 40.082969 Longitude: -108.230001

FACILITY - API Number: 05-103-00 Facility ID: 231846

Facility Name: MOBIL-JACOBS Number: 1-3

Qtrqtr: NESW Sec: 1 Twp: 1N Range: 97W Meridian: 6

Latitude: 40.082969 Longitude: -108.230001

CORRECTIVE ACTIONS:

2 CA# 191526

Corrective Action: The Operator will conspicuously post and maintain the date of the last meter calibration in a legible condition at each meter at all times.

Date: 05/08/2023

Response: CA COMPLETED

Date of Completion: 03/06/2025

Operator Comment: Per inspection 715501392 at this location, dated 3/6/2025, this corrective action has been resolved.

ECMC Decision: _____

ECMC Representative: _____

3 CA# 191527

Corrective Action: Perform successful mechanical integrity test. If a successful MIT cannot be performed within 30 day CA time the well must be plugged within 3 months.

Date: 05/21/2023

Response: CA COMPLETED

Date of Completion: 03/06/2025

Operator Comment: Per inspection 715501392 at this location, dated 3/6/2025, this corrective action has been resolved.

ECMC Decision: _____

ECMC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Amber Barnett

Signed: _____

Title: Compliance Specialist

Date: 4/30/2026 11:50:26 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
404635580	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files