

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/01/2026

Submitted Date:

05/01/2026

Document Number:

708909065

FIELD INSPECTION FORM

Loc ID 323778 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Findings:

- 4 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
TEP		ECMCInspectionReports@flywheelenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210784	WELL	PR	09/03/1987	GW	045-06542	MOBIL W-18-27	PR
265373	WELL	PR	02/09/2026	GW	045-08998	PA 314-27	PR

General Comment:

[This is a Desktop Inspection/Audit of the scout card & related documents.](#)

Inspected Facilities

Facility ID: 210784 Type: WELL API Number: 045-06542 Status: PR Insp. Status: PR

Producing Well

Comment:	WBD submitted 01/14/2026 - FORM 4 SUNDRY document # 404505169	
Corrective Action:		Date:

Facility ID: 265373 Type: WELL API Number: 045-08998 Status: PR Insp. Status: PR

Producing Well

Comment:	WBD submitted 01/14/2026 - FORM 4 SUNDRY document # 404505237	
	FORM 5A submitted 02/09/2026 - document # 404537654	
Corrective Action:		Date:

ECMC Comments

Comment	User	Date
<p>CECMC Inspection/Audit Report Summary On 05/01/2026 at approximately 10:45 hours, I, Compliance Specialist, Wayne Smelser Conducted a desktop follow up inspection/audit of TEP ROCKY MOUNTAIN LLC MOBIL W-18-27 Location # 323778 in Garfield County Colorado. Please refer to inspection/audit 708908058 conducted on 12/15/2025, previous corrective actions have been completed. Location is within High Priority/Density Habitat areas & in close proximity to NSO/Black Bear Habitat areas. Location is within Rule 411a Surface Water Intermediate Buffer.</p> <p>This is a summary of desktop inspection/audit report.</p>	smelserw	05/01/2026