

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/23/2026

Submitted Date:

04/26/2026

Document Number:

693809231

FIELD INSPECTION FORM

Loc ID 316860 Inspector Name: BROWNING, CHUCK On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

14 Number of Comments

1 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

ECMC Operator Number: 10841

Name of Operator: AMERICAN HELIUM LLC

Address: 23501 CINCO RANCH BLVD, B244

City: KATY State: TX Zip: 77494

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Lapham, Ken	979-877-4951	klapham@americanhelium.us	All Inspections
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Harrison, Trish	970-759-9545	trish.harrison@coolskyenergy.com	
Pesicka, Conor		conor.pesicka@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	
		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
283719	WELL	TA	01/01/2017	GW	113-06210	MD FED 28-32-45-15	TA

General Comment:

[ECMC Inspection/Audit Report Summary](#)

On April 23, 2026, ECMC Compliance Specialist Chuck Browning, conducted an onsite inspection for AMERICAN HELIUM LLC 10481 on the MD Fed 28-32-45-15 well, API# 113-06210, Loc ID#316860, in San Miguel County, Colorado.

The well was Temporarily Abandoned.

During the inspection/audit, the following compliance issues were observed:

1) Past due MIT to maintain SI/TA status

Any corrective action(s) from previous inspection that have not been addressed are still applicable

Location

Lease Road:			
Type	Main		
comment:	HWY 141		
Corrective Action			Date:
Type	Access		
comment:	Co Rd 29Y		
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign on meter housing		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	435-631-2239		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panel fence		
Corrective Action:			Date:
Type	LOCATION		
Comment:	Livestock		
Corrective Action:			Date:

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Disconnected and Blind flanged.		
Corrective Action:			Date:

Type: Horizontal Heated Separator	# 0	
Comment:	Equipment removed	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				
Comment:	Tank battery removed				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 283719 Type: WELL API Number: 113-06210 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Last production 11/30/2014. Defined inactive 1/1/2017.
Last MIT to maintain SI/TA status 11/19/2019 .
Well is overdue for Mechanical Integrity Test (MIT). MIT require 10 day notification via Form 42.

Corrective Action: Perform successful mechanical integrity test per Rule 417. Operator has 30 days to perform the required MIT. Date: 05/29/2026

BradenHead

Date of Last Brhd Test: 08/12/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Ditches	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>On April 23, 2026, ECMC Compliance Specialist Chuck Browning, conducted an onsite inspection for AMERICAN HELIUM LLC 10481 on the MD Fed 28-32-45-15 well, API# 113-06210, Loc ID#316860, in San Miguel County, Colorado.</p> <p>The well was Temporarily Abandoned.</p> <p>During the inspection/audit, the following compliance issues were observed: 1) Past due MIT to maintain SI/TA status</p>	browninc	04/26/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404634243	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7526778
693809243	Inspection photos 4/23/2026	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7526774