

Inspection Photos
David Howard Flowline Release
Spill ID 484274/Remediation No 40353



Photo 1 – Excavation has been backfilled with trash.

Photo 2 – Stained soil visible next to filled excavation.