

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404645715

Date Received:  
05/04/2026

**FIR RESOLUTION FORM**

**Overall Status:**

CA Summary:

2 of 7 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

**OPERATOR INFORMATION**

ECMC Operator Number: 10734  
Name of Operator: HIGH RIVER RESOURCES OPERATING LLC  
Address: 3838 OAK LAWN AVE SUITE 750  
City: DALLAS State: TX Zip: 75219

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Archuleta, Amy</u>		<u>aarchuleta@highriverllc.com</u>

**ECMC INSPECTION SUMMARY:**

FIR Document Number: 721100355  
Inspection Date: 04/23/2026 FIR Submit Date: 04/27/2026 FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: HIGH RIVER RESOURCES OPERATING LLC Company Number: 10734  
Address: 3838 OAK LAWN AVE SUITE 750  
City: DALLAS State: TX Zip: 75219

**LOCATION** - Location ID: 333517

Location Name: BONDAD 34-10-M34N10W Number: 36NWSE County: LA PLATA  
Qtrqtr: NWSE Sec: 36 Twp: 34N Range: 10W Meridian: M  
Latitude: 37.144740 Longitude: -107.881780

**FACILITY** - API Number: 05-067-00 Facility ID: 214279

Facility Name: BONDAD 34-10 Number: 1-36  
Qtrqtr: NWSE Sec: 36 Twp: 34N Range: 10W Meridian: M  
Latitude: 37.144740 Longitude: -107.881780

**CORRECTIVE ACTIONS:**

**2** CA# 212446

Corrective Action: Cleanup stained material and dispose in approved facility and review self inspection processes to comply with 1002.f.(2).D Date: 05/04/2026

Response: CA COMPLETED Date of Completion: 04/30/2026

Operator Comment: This corrective action is complete.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**7** CA# 212451

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.  
  
Repair wildlife protection equipment (repair and close curtains) and prevent any unauthorized discharge of lube oil/antifreeze (increase spill response measures) to comply with 902.b

Date: 05/12/2026

Response: CA COMPLETED

Date of Completion: 04/30/2026

Operator  
Comment: This corrective action is complete.

This corrective action is complete.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: CA #2 and #7 have been resolved,

CA #2 and #7 have been resolved,

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Amy Archuleta

Signed: \_\_\_\_\_

Title: Regulatory Manager

Date: 5/4/2026 2:36:49 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
404645715	FIR RESOLUTION SUBMITTED
404645730	Documentation of stained soil clean up,

Total Attach: 2 Files