

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/30/2026

Submitted Date:

04/30/2026

Document Number:

697012730

FIELD INSPECTION FORM

Loc ID 422731 Inspector Name: Peterson, Tom On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10633
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
Address: 555 17TH STREET SUITE 3700
City: DENVER State: CO Zip: 80202

Findings:

- 14 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
422715	WELL	PR	07/01/2025	GW	123-33363	FREDERIKSEN 1A-28H	PR
433504	WELL	PR	09/01/2020	OW	123-37667	Frederiksen 1B-28H-H368	PR
433506	WELL	PR	12/01/2019	OW	123-37668	Frederiksen 1C-28H-H368	PR

General Comment:

[This is a field audit of the scout card, related documents and the location.](#)

Location

Overall Good:

Signs/Marker:			
Type	OTHER		
Comment:	Lease entrance sign		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	x 3		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			Date: _____
Corrective Action:			

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused wellhead flange, flow tee and polish rod on west edge of location, see attached photos.		
Corrective Action:	Comply with Rule 606.		Date: 06/01/2026

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Sound wall at hydraulic pumping unit powerpack		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Architectural steel.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 3		
Comment:	Bradenhead valves are exposed at surface.		
Corrective Action:		Date:	
Type: Flow Line	# 3		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	#		
Comment:	Automation array, hydraulic pumping unit powerpack and electrical systems		
Corrective Action:		Date:	

Type: Prime Mover	# 1		
Comment:	Natural gas engine		
Corrective Action:			Date:
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		
Comment:	Tank battery #480376				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 422715 Type: WELL API Number: 123-33363 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Facility ID: 433504 Type: WELL API Number: 123-37667 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Facility ID: 433506 Type: WELL API Number: 123-37668 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>ECMC Audit Report Summary On Thursday 4/30/2026 at approximately 13:15 hours I, Inspector Tom Peterson, conducted an on-site inspection at the Crestone Peak Frederiksen 63N-68W 1A-28H Pad location #422731 in Weld County, Colorado. While there, I observed unused equipment on the location. During this inspection the following possible compliance issues were observed: Rule 606. with a corrective action date of 6/1/2026. A follow up inspection on this site needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules. This is a summary of the inspection report.</p>	petersont	04/30/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404642197	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7533708
697012731	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7533705