

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/29/2026

Submitted Date:

04/30/2026

Document Number:

710500781

**FIELD INSPECTION FORM**

Loc ID 322234 Inspector Name: Sanchez, Chris On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10417  
Name of Operator: INCREMENTAL OIL & GAS (FLORENCE) LLC  
Address: 113 N SANTA FE AVE  
City: FLORENCE State: CO Zip: 81226

**Findings:**

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Waggoner, Kyle		kyle.waggoner@state.co.us	
Harkins, Liz	719-429-4513	Lharkins@austinexploration.com	<a href="#">All Inspections</a>
Hart, Tim	309-999-5420	thart@fremontpetroleum.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
295254	WELL	PA	12/01/2022	OW	043-06150	RAINBOW 23-20	EI
490760	SPILL OR RELEASE	CL	06/27/2025		-	Rainbow 23-20 Historical Release	EI

**General Comment:**

This is a follow up Environmental Inspection for the Rainbow 23-20 well location, located in Fremont County, Colorado.

API: 05-043-06150  
Location ID: 322234  
Spill ID 490760  
Rem #: 37633  
Inspection # 710500721  
Inspection # 710500665

**Inspected Facilities**

Facility ID: 295254 Type: WELL API Number: 043-06150 Status: PA Insp. Status: EI

Facility ID: 490760 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

**Environmental**

**Spill/Remediation:**

Comment:

This is an Environmental Inspection for Remediation Project # 37633. At the time of inspection, open excavations located at the former tank battery located on the western edge of the well location have been backfilled. The contaminated spoil pile observed within the lined containment on location has been recently disturbed with a reduction in the amount of soil staged within the lined contaminated. Operator shall provide Waste Manifests for the removal of contaminated soils from remediation project # 37633.

In addition, the Operator shall provide all recent and historical analytical data for the delineation of impacted soils associated with Remediation Project # 37633.

The last quarterly update for Remediation Project # 37633 was received on 08/27/2025, Form 27-S document no. 404331965. The quarterly update (90-day) was due on November 25, 2025. Operator shall submit a Supplemental Form 27-S, for Remediation Project # 37633 and update the implementation schedule in accordance with Rule 913.

In addition, Operator will provide an explanation for late reporting on the next Form 27 Supplemental including actions implemented to prevent late reporting in the future.

In accordance with Rule 913.e., Operator will adopt a quarterly reporting schedule (every 90 days). Operator shall provide a current map of the subject location including current excavation limits and/or sample locations, proposed/actual soil boring locations and monitoring well locations. GPS data used to create the map must comply with ECMC Rule 216.

Corrective Action:

The Original Corrective Action Date of 1/29/2026 shall apply.

Date: 01/29/2026

Emission Control Burner (ECB): \_\_\_\_\_

Comment:

\_\_\_\_\_

Pilot: \_\_\_\_\_

Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There is erosion along the access road and along the cut/fill slopes of the location. Areas of erosion must be repaired and stabilized. Previous corrective action was not completed.

Install or repair required BMPs per Rule 1002.f.(2)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<span style="color: blue;">All ongoing/unaddressed comments, Corrective Actions (CAs) and Conditions of Approval (COAs) from previous Forms remain applicable.</span>	sanchezcc	04/30/2026

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404642494	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7534017">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7534017</a>
710500782	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7534015">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7534015</a>
710500783	Inspection Photos Inspection Doc # 710500721	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7534016">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7534016</a>