

FORM
INSPRev
X/20

State of Colorado
Energy and Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/18/2026

Submitted Date:

05/18/2026

Document Number:

719002012

FIELD INSPECTION FORM

Loc ID 326147 Inspector Name: GARCIA, CHARLES On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10133
 Name of Operator: HILCORP ENERGY COMPANY
 Address: P O BOX 61229
 City: HOUSTON State: TX Zip: 77208

Findings:

4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, General		FarmingtonRegulatoryTechs@hilcorp.com	SJB inspect

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215946	WELL	PR	04/12/2000	CBM	067-07551	HUBER-LOBATO 1-26	PR

General Comment:

Inspection Report Summary
 On 5/18/26 | Inspector Charles Garcia
 conducted an LAPTOP inspection.
 Location: HUBER-LABATO 1-26
 API# 067-07551
 Operator: HILLCORP ENERGY COMPANY
 County: LaPlata
 All prior CA's still stand.
 FIR#719001840
 FIRR#404646338
 CA'S RESOLVED

Inspected Facilities

Facility ID: 215946 Type: WELL API Number: 067-07551 Status: PR Insp. Status: PR

Producing Well

Comment: PR
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 04/07/2026 Annual Brhd Completed? Yes
 Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
 End Surf Csg Pressure: 0
 Comment: _____
 Corrective Action: _____ Date: _____

ECMC Comments

Comment	User	Date
<p>EAST SIDE OF LOCATION UNUSED EQUIPMENT AND 5 GAL LEAKING BUCKET SEE Corrective Action: Unnecessary equipment COMPLPY WITH RULE 606 LEAK ON ENGINE FOR PRIME MOVER HAS CAUSED OIL TO LEAK ON BOTH SIDES OF ENGINE SKID Corrective Action: MAINTAIN ENGINE RULE 608.e AND CLEAN UP IMPACTED SOIL AROUND PRIME MOVER SKID rule 1002.f CA'S RESOLVED SEE LOCATION PICTURES FIR#404646338</p>	garciacr1	05/18/2026