

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/21/2026

Submitted Date:

05/21/2026

Document Number:

713302697

FIELD INSPECTION FORM

Loc ID 415021 Inspector Name: Kester, Michael On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10459
Name of Operator: EXTRACTION OIL & GAS INC
Address: 555 17TH STREET SUITE 3700
City: DENVER State: CO Zip: 80202

Findings:

- 9 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, CivitasResources		Inspections@civiresources.com	all inspections
Santistevan, Brittani		brittani.santistevan@state.co.us	
Burn, Diana		diana.burn@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451205	WELL	PR	11/01/2025	OW	123-45021	Wake North Fed 33W-25-22	PR

General Comment:

[well site inspection](#)

Location

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:	Well name sign at the well doesn't reflect what is in the ECMC data base. Submit proper documentation and correct designated well sign. Sign posted or information inaccurate at well		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	06/22/2026

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

	Type WELLHEAD		
Comment:	metal panels		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Ancillary equipment # 3			
Comment: automation			
Corrective Action:		Date:	
Type: Bradenhead # 1			
Comment: piped to surface			
Corrective Action:		Date:	
Type: Plunger Lift # 1			
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No NO

Comment:

Corrective Action: Date: _____

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 451205 Type: WELL API Number: 123-45021 Status: PR Insp. Status: PR

Producing Well

Comment: Valves appeared to be closed at time of inspection
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 04/28/2025 Annual Brhd Completed? No
 Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
 End Surf Csg Pressure: 0
 Comment: submit report
 Corrective Action: _____ Date: _____

ECMC Comments

Comment	User	Date
Inspector Michael Kester, did audit scout card and related documents conducted on-site inspection, Location: Wake North Fed 33W-25-22 Operator: Extraction API#: 123-45021 County: Weld While there, I observed multi well site, During this inspection the following possible compliance issues were observed: Sign, Rule 605d, corrective action date 6-22-2026 Weather conditions: sunny and dry A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules. This inspection does not nullify any orders or NOAV from the ECMC	kesterm	05/21/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404668970	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7556700
713302698	site pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7556698