

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/20/2026

Submitted Date:

05/27/2026

Document Number:

719201197

FIELD INSPECTION FORM

Loc ID 312860 Inspector Name: Gaasche, Emily On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 95520
Name of Operator: WESCO OPERATING INC
Address: 120 S DURBIN STREET
City: CASPER State: WY Zip: 82602

Findings:

- 5 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Brian Meidinger		brianm@kirkwoodcompanies.com	
Parker Coit		parker.coit@wsp.com	
Dave Weinert		davew@kirkwoodcompanies.com	
Josh Knigge		joshk@kirkwoodcompanies.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222648	WELL	SI	07/01/2024	DSPW	081-06008	MAUDLIN GULCH UNIT 12	RI
312860	LOCATION	AC			-	MAUDLIN GULCH UNIT-64N95W 27SWNW	RI

General Comment:

On 05/20/2026, NW Reclamation Specialist Emily Gaasche conducted a reclamation inspection at Wesco Operating Inc's MAUDLIN GULCH UNIT-64N95W/27SWNW (Maudlin Gulch Unit #12) location in Moffat County, Colorado.

The location is within CPW High Priority Habitat: Elk Migration Corridor, Elk Production Area.

The following compliance issues were observed during this inspection:

- Fencing around open excavation down
- Stormwater (cut slope stabilization)

Refer to the Location, Reclamation and Stormwater sections of this report for additional details.

Refer to the photo-documentation attached to this report for additional details.

Any outstanding CA's from previous inspections remain applicable.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type WELLHEAD

Comment: Orange plastic fencing surrounding the open excavation is down. Maintenance to prevent livestock and wildlife access is required.

Corrective Action: Install or repair wildlife protection BMP's to comply with Rule 902.b.

Date: 06/10/2026

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 222648 Type: WELL API Number: 081-06008 Status: SI Insp. Status: RI

Facility ID: 312860 Type: LOCATION API Number: - Status: AC Insp. Status: RI

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Corrective Action

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment:

Pursuant to Form 6(s) #404234056, the well was PA'd on 6/1/2025. An active remediation project (#40827) is occurring at the location; an open excavation is present. No noxious weed issues were observed at the time of inspection. Ongoing weed monitoring and maintenance is required until the location receives a passing final reclamation inspection.

A follow-up inspection will be conducted during future growing seasons to evaluate reclamation progress and compliance with 1004.

Corrective Action:

Date

Overall Final Reclamation

Well Release on Active Location

Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Portions of the cut slopes are predominantly bare in some places; additional stabilization efforts are required.

Corrective Action: Comply with Rule 1002.f.

Date:

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Additional Reclamation Comments: Operator notes that the downhill side of this location will be recontoured and reseeded, and that the access road and uphill side of the location will remain. Any work to be done in a manner that does not comport with ECMC rules requires a variance pursuant to Rules 502 and 510.	gaaschee	05/27/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404674631	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7561006
719201198	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7561005