

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/28/2026

Submitted Date:

05/28/2026

Document Number:

715802319

FIELD INSPECTION FORM

Loc ID 318975 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1700 LINCOLN ST STE 4550
City: DENVER State: CO Zip: 80203

Findings:

- 23 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242625	WELL	PR	03/01/2022	OW	123-10416	PRATT 2	PR
421605	WELL	PR	03/01/2022	OW	123-32971	SRC Pratt 24-29D	PR
421628	WELL	PR	07/01/2025	OW	123-32981	SRC Pratt 13-29D	PR
421642	WELL	PR	06/01/2024	OW	123-32988	SRC Pratt 14-29D	PR

General Comment:

[This is a FIR in response to Complaint Doc # 200452729](#)

Location

Lease Road:			
Type			
comment:	Needs attention by the entrance		
Corrective ActionL		Date:	

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	adequate x 4		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:		Date:	_____

Good Housekeeping:			
Type	OTHER		
Comment:	Stained soil identified at various locations through out location. Tank battery, wellheads		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002..(2).D	Date:	06/03/2026

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	IGNITOR/COMBUSTOR		
Comment:	Custom metal panel		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Custom metal panel		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Red & green ag panel		
Corrective Action:		Date:	

Type	SEPARATOR		
Comment:	Shares with ignitor/combustor		
Corrective Action:		Date:	

Equipment:

Type: Emission Control Device	# 2		corrective date
Comment:	1 appears to be SI the other appears to be PR with no pilot lit, I spoke with KPK representative to have a lease operator go out & get the pilot lit.		
Corrective Action:		Date:	
Type:	#		
Comment:	No change from previous FIR		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:	No change from previous FIR				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Wells Served By Facilities Above

API Number
123-32981
123-32971
123-32988
123-10416

AirsID

API Number	AirsID

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 242625 Type: WELL API Number: 123-10416 Status: PR Insp. Status: PR

Producing Well

Comment: PR
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 06/27/2025 Annual Brhd Completed? Yes
 Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
 End Surf Csg Pressure: 0
 Comment: Piped to surface
 Corrective Action: _____ Date: _____

Facility ID: 421605 Type: WELL API Number: 123-32971 Status: PR Insp. Status: PR

Producing Well

Comment: PR
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 03/31/2026 Annual Brhd Completed? Yes
 Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE
 End Surf Csg Pressure: 0
 Comment: Piped to surface
 Corrective Action: _____ Date: _____

Facility ID: 421628 Type: WELL API Number: 123-32981 Status: PR Insp. Status: PR

Producing Well

Comment: PR
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 01/30/2026 Annual Brhd Completed? Yes
 Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE
 End Surf Csg Pressure: 0
 Comment: Piped to surface
 Corrective Action: _____ Date: _____

Facility ID: 421642 Type: WELL API Number: 123-32988 Status: PR Insp. Status: PR

Producing Well

Comment: PR
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 02/27/2026 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: Piped to surface

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>ECMC Inspection Report Summary On Thursday 5-28-2026 at approximately 1000 hrs. I, Inspector Robbie Revas, Conducted an audit of the well scout card & related forms followed by an onsite inspection: Operator: KP Kauffman Location # 318975 API # 05- Well name: SRC Pratt 24-29D County: Weld Weather: Cloudy Temp: 66* Location: dry While there, I observed a wellsite & tank battery, PR at the time of inspection. During this inspection the following possible compliance issues were observed: 1002..(2).D housekeeping: Stained soil needs to be removed CA date 6-3-2026. Any corrective actions from previous Inspections that have not been addressed are still applicable. See attached photos. I spoke with Mani Silva KP Kauffman Rep. about the issues & he stated that he would get ahold of the lease operator & get the issues taken care of. A follow up on this site inspection will be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules. This inspection does not nullify any orders or NOAV from the ECMC, any corrective actions from previous inspections that have not been addressed are still applicable.</p>	revasr	05/28/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404676403	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7562269
715802320	Location photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7562265