

FORM
INSPRev
X/20

State of Colorado Energy and Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/09/2026

Submitted Date:

05/29/2026

Document Number:

709100660

FIELD INSPECTION FORM

Loc ID 317135 Inspector Name: Heibel, Krystal On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10808
 Name of Operator: COPPER LAND RESOURCES LLC
 Address: 9470 HOMESTEAD DR
 City: FREDERICK State: CO Zip: 80504

Findings:

- 5 Number of Comments
3 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Kyle Waggoner		kyle.waggoner@state.co.us	
Krystal Heibel		krystal.heibel@state.co.us	
Jany, Josh		jdjany@hotmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
236707	WELL	PR	12/01/2025	OW	121-09200	CHRISTIANSON B 3	EI

General Comment:

This is an environmental inspection. Any corrective actions from previous inspections that have not been addressed are still applicable.
 On April 9, 2026, ECMC Staff Krystal Heibel and Alex Ahmadian conducted an environmental remediation inspection at this location.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

Comment: Burrows observed on location

Corrective Action:

Date:

Type

Comment: Unused equipment and weeds observed

Corrective Action: Comply with Rule 606

Date: 05/13/2026

Type

Comment: Wildlife protections devices not adequate - see photo 1

Corrective Action: Repair wildlife protection equipment

Date: 06/03/2026

Overall Good:

Spills:

Type

Area

Volume

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 236707 Type: WELL API Number: 121-09200 Status: PR Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: _____ Estimated Spill Volume: _____

Comment: Hydrocarbon stained soil observed on location and at wellhead - see photos 5 and 7

Corrective Action: Properly remediate and dispose in accordance with Rule 912. Date: 06/03/2026

Reportable: _____ GPS: Lat _____ Long _____

Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404677664	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7563448
709100661	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7563438