WELLHEAD ABANDONMENT FORM

SITE NAME: Babcock 14C, 33C-33HZ	**DATE:** 3/27/2024	**REM. PROJECT #:**
WEATHER: Sunny, 40s/50s		
SITE DIRECTIONS: CR 17/26 head E 500 m then turn S into site and follow access road past the TB to WHs	**CLIENT:** Oxy	
LEGALS AND LAT/LONG: 40.169186, -104.897374	**TASMAN PERSONNEL:** SD	
SOIL TYPES: Clayey Sand - SC	**SURFACE GRADIENT:** South	

SOIL SAMPLING

Date/Time	Soil Sample ID	PID (ppm)	Visual	Olfactory	Photo?	Grab or Lab Sample?
3/27/2024 14:30	14C-WH-B01@6'	8.1	No Staining	No Odor	Yes	Lab
3/27/2024 14:32	14C-FL-B01@4'	3.9	No Staining	No Odor	Yes	Lab
3/27/2024 14:34	14C-WH-N01@5'	0.3	No Staining	No Odor	Yes	N/A
3/27/2024 14:36	14C-WH-S01@5'	76.8	No Staining	Slight HC Odor	Yes	Lab
3/27/2024 14:38	14C-WH-E01@5'	0.8	No Staining	No Odor	Yes	N/A
3/27/2024 14:40	14C-WH-W01@5'	0.3	No Staining	No Odor	Yes	N/A
3/27/2024 14:42	14C-WHS-N01@3"	0.0	No Staining	No Odor	Yes	N/A
3/27/2024 14:44	14C-WHS-S01@3"	0.4	No Staining	No Odor	Yes	N/A
3/27/2024 14:46	14C-WHS-E01@3"	0.0	No Staining	No Odor	Yes	N/A
3/27/2024 14:48	14C-WHS-W01@3"	0.0	No Staining	No Odor	Yes	N/A
3/27/2024 14:50	33C-WH-B01@6'	24.8	No Staining	No Odor	Yes	Lab
3/27/2024 14:52	33C-FL-B01@4'	0.2	No Staining	No Odor	Yes	Lab
3/27/2024 14:54	33C-WH-N01@5'	0.0	No Staining	No Odor	Yes	N/A
3/27/2024 14:56	33C-WHS-N01@3"	0.0	No Staining	No Odor	Yes	N/A
3/27/2024 14:58	33C-WHS-S01@3"	0.2	No Staining	No Odor	Yes	N/A
3/27/2024 15:00	33C-WHS-E01@3"	0.0	No Staining	No Odor	Yes	N/A
3/27/2024 15:02	33C-WHS-W01@3"	0.1	No Staining	No Odor	Yes	N/A
3/27/2024 15:04	BG01@3'	0.3	No Staining	No Odor	Yes	Lab
3/27/2024 15:06	BG01@6'	0.2	No Staining	No Odor	Yes	Lab
3/27/2024 15:08	BG02@3'	0.1	No Staining	No Odor	Yes	Lab
3/27/2024 15:10	BG02@6'	0.0	No Staining	No Odor	Yes	Lab
3/27/2024 15:12	BG03@3'	0.1	No Staining	No Odor	Yes	Lab

FACILITY INFRASTRUCTURE

EQUIPMENT	Quantity
Above Ground Storage Tank (AST)	
Buried or Partially Buried Vessel	
Separator	
Emission Control Device (ECD)	
Dump Line	
Wellhead	
Flowline	
Other:	

Soil Loads Removed

IMPACTED SOIL IDENTIFIED?

ESTIMATED VOLUME OF IMPACTS:

Date	Number	CY
Total Removed	0	0

Disposal Facility:

Groundwater Recovery

DATE GW ENCOUNTERED: **DEPTH:**

GROUNDWATER IN CONTACT WITH IMPACTED SOIL?

LNAPL OR SHEEN OBSERVED ON GW?

Date	BBLS
Total Removed	0

Disposal Facility:

GROUNDWATER SAMPLING

Date/Time	Groundwater Sample ID	Depth Collected	Turbid?	Sheen?	Odor?	Photo?

WELLHEAD ABANDONMENT FORM

SITE NAME: Babcock 14C, 33C-33HZ	**DATE:** 3/27/2024	**REM. PROJECT #:**	**WEATHER:** Sunny 40s/50s
SITE DIRECTIONS: CR 17/26 head E 500 m then turn S into site and follow access road past the TB to WHs	**CLIENT:** Oxy		
LEGALS AND LAT/LONG: 40.169186, -104.897374	**TASMAN PERSONNEL:** SD		
SOIL TYPES: Clayey Sand - SC	**SURFACE GRADIENT:** South		

SOIL SAMPLING

Date/Time	Soil Sample ID	PID (ppm)	Visual	Olfactory	Photo?	Grab or Lab Sample?
3/27/2024 15:14	BG03@6'	0.3	No Staining	No Odor	Yes	Lab
3/27/2024 15:16	BG04@3'	0.2	No Staining	No Odor	Yes	Lab
3/27/2024 15:18	BG04@6'	0.1	No Staining	No Odor	Yes	Lab
3/27/2024 15:20	BG05@3'	0.1	No Staining	No Odor	Yes	Lab
3/27/2024 15:22	BG05@6'	0.1	No Staining	No Odor	Yes	Lab
4/3/2024 12:45	14C-WH-S01R@5'	0.7	No Staining	No Odor	Yes	Lab

FACILITY INFRASTRUCTURE

EQUIPMENT	Quantity
Above Ground Storage Tank (AST)	
Buried or Partially Buried Vessel	
Separator	
Emission Control Device (ECD)	
Dump Line	
Wellhead	
Flowline	
Other:	

Soil Loads Removed

IMPACTED SOIL IDENTIFIED?

ESTIMATED VOLUME OF IMPACTS:

Date	Number	CY
Total Removed	0	0

Disposal Facility:

Groundwater Recovery

DATE GW ENCOUNTERED: **DEPTH:**

GROUNDWATER IN CONTACT WITH IMPACTED SOIL?

LNAPL OR SHEEN OBSERVED ON GW?

Date	BBLS
Total Removed	0

Disposal Facility:

GROUNDWATER SAMPLING

Date/Time	Groundwater Sample ID	Depth Collected	Turbid?	Sheen?	Odor?	Photo?

TASMAN GEOSCIENCES

Photographic Log



Equipment ID:	Equipment Type:	
Material:	Volume:	Contents:
Notes/Conditions:		

Equipment ID:	Equipment Type:	
Material:	Volume:	Contents:
Notes/Conditions:		

TASMAN GEOSCIENCES

Photographic Log

Equipment ID:	Equipment Type:	
Material:	Volume:	Contents:
Notes/Conditions:		

Equipment ID:	Equipment Type:	
Material:	Volume:	Contents:
Notes/Conditions:		

TASMAN GEOSCIENCES

Photographic Log

Equipment ID:	Equipment Type:	
Material:	Volume:	Contents:
Notes/Conditions:		

Equipment ID:	Equipment Type:	
Material:	Volume:	Contents:
Notes/Conditions:		

TASMAN GEOSCIENCES

Photographic Log

Equipment ID:	**Equipment Type:**		**Equipment ID:**	**Equipment Type:**	
Material:	**Volume:**	**Contents:**	**Material:**	**Volume:**	**Contents:**
Notes/Conditions:			**Notes/Conditions:**		

TASMAN GEOSCIENCES

Photographic Log

Equipment ID:	**Equipment Type:**		**Equipment ID:**	**Equipment Type:**	
Material:	**Volume:**	**Contents:**	**Material:**	**Volume:**	**Contents:**
Notes/Conditions:			**Notes/Conditions:**		