

FORM
17
Rev
6/99

State of Colorado
Energy & Carbon Management Commission



DE	ET	OE	ES
----	----	----	----

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
401262686

BRADENHEAD TEST REPORT

Step 1. Record all tubing and casing pressures as found. Step 2. Sample now. If intermediate or surface casing pressure > 25 psi. In sensitive areas, 1 psi.
Step 3. Conduct Bradenhead test. Step 4. Conduct intermediate casing test. Step 5. Send report to BLM within 3 days and to ECMC within 10 days. Include wellbore diagram if not previously submitted or if wellbore configuration has changed since prior program. Attach gas and liquid analyses if sampled.

1. ECMC Operator Number: 10459 3. BLM Lease No: _____
 2. Name of Operator: EXTRACTION OIL & GAS LLC
 4. API Number; 05-123-41110-00 5. Multiple completion? Yes No
 6. Well Name: Arellano Number: O-10-9HN
 7. Location (QtrQtr, Sec, Twp, Rng, Meridian): NESE,10,5N,65W,6
 8. County WELD 9. Field Name: WATTENBERG
 10. Minerals: Fee State Federal Indian

11. Date of Test: 01/19/2017
 12. Well Status: Flowing
 Shut In Gas Lift
 Pumping Injection
 Clock/Intermitter
 Plunger Lift
 13. Number of Casing Strings:
 Two Three Liner?

14. EXISTING PRESSURES

Record all pressures as found	Tubing: <u>400</u> Fm: _____	Tubing: _____ Fm: _____	Prod Csg <u>650</u> Fm: _____	Intermediate _____ Csg: _____	Surf. Csg _____ 0
-------------------------------	---------------------------------	----------------------------	----------------------------------	----------------------------------	----------------------

BRADENHEAD TEST

Buried valve? Yes No
 Confirmed open? Yes No
 With gauges monitoring production, intermediate casing and tubing pressures, open surface casing (bradenhead) valve (if no intermediate casing, monitor only the production casing and tubing pressures.) Record pressures at five minute intervals Define characteristics of flow in "Bradenhead Flow" column using letter designations below:
 O = No Flow; C = Continuous; D = Down to 0; V = Vapor
 H = Water H2O; M = Mud; W = Whisper; S = Surge; G = Gas

BRADENHEAD SAMPLE TAKEN?
 Yes No Gas Liquid
 Character of Bradenhead fluid: Clear Fresh
 Sulfur Salty Black
 Other:(describe) _____
 Sample cylinder number: _____

Elapsed Time (Min:Sec)	Fm: Tubing	Fm: Tubing:	Prod Csg PSIG	Intermedia Csg PSIG	Bradenhead Flow:
00:00	<input type="checkbox"/> 400	<input type="checkbox"/>	<input type="checkbox"/> 650	0	DOWN TO 0
05:00	<input type="checkbox"/> 400	<input type="checkbox"/>	<input type="checkbox"/> 650	0	DOWN TO 0
10:00	<input type="checkbox"/> 400	<input type="checkbox"/>	<input type="checkbox"/> 650	0	DOWN TO 0
15:00	<input type="checkbox"/> 400	<input type="checkbox"/>	<input type="checkbox"/> 650	0	DOWN TO 0
20:00	<input type="checkbox"/> 400	<input type="checkbox"/>	<input type="checkbox"/> 650	0	DOWN TO 0
25:00	<input type="checkbox"/> 400	<input type="checkbox"/>	<input type="checkbox"/> 650	0	DOWN TO 0
30:00	<input type="checkbox"/> 400	<input type="checkbox"/>	<input type="checkbox"/> 650	0	DOWN TO 0

Instantaneous Bradenhead PSIG at end of test: > 0

INTERMEDIATE CASING TEST

Buried valve? Yes No
 Confirmed open? Yes No
 With gauges monitoring production, intermediate casing and tubing pressures, open the intermediate casing valve. Record pressures at five minute intervals Characterize flow in "Intermediate Flow" column using letter designations below:
 O = No Flow; C = Continuous; D = Down to 0; V = Vapor
 H = Water H2O; M = Mud; W = Whisper; S = Surge; G = Gas

INTERMEDIATE SAMPLE TAKEN?
 Yes No Gas Liquid
 Character of Intermediate fluid: Clear Fresh
 Sulfur Salty Black
 Other:(describe) _____
 Sample cylinder number: _____

Elapsed Time (Min:Sec)	Fm: Tubing	Fm: Tubing:	Prod Csg PSIG	Intermedia Csg PSIG	Bradenhead Flow:
00:00	<input type="checkbox"/> 400	<input type="checkbox"/>	<input type="checkbox"/> 650		
05:00	<input type="checkbox"/> 400	<input type="checkbox"/>	<input type="checkbox"/> 650		
10:00	<input type="checkbox"/> 400	<input type="checkbox"/>	<input type="checkbox"/> 650		
15:00	<input type="checkbox"/> 400	<input type="checkbox"/>	<input type="checkbox"/> 650		
20:00	<input type="checkbox"/> 400	<input type="checkbox"/>	<input type="checkbox"/> 650		
25:00	<input type="checkbox"/> 400	<input type="checkbox"/>	<input type="checkbox"/> 650		
30:00	<input type="checkbox"/> 400	<input type="checkbox"/>	<input type="checkbox"/> 650		

Instantaneous Intermediate Casing PSIG at end of test: >

Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Test Performed By: Robert Brockett Title: Pressure Testing Lead Phone: (346) 802-8879

Signed: Sara Mason Title: Environmental
Professiona Date: 4/26/2017

Witnessed By: Title: Agency: