

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303)894-2100 Fax: (303)894-2109



02577076



DE ET DE ES

RECEIVED

MAR 25 2010

COGCC/Rifle Office

Submit original plus one copy. This form is to be used for general, technical and environmental sundry information. For proposed or completed operations, describe in full on Technical Information Page (Page 2 of this form). Identify well or other facility by API Number or by OGCC Facility ID. Operator shall send an informational copy of all sundry notices for wells located in High Density Areas to the Local Government Designee (Rule 603b.)

1. OGCC Operator Number:	100185	4. Contact Name	
2. Name of Operator:	ENCANA OIL & GAS (USA) INC	DeAnne Spector	
3. Address:	370 17TH ST, STE 1700	Phone:	720-876-5826
City:	DENVER	State:	CO
Zip:	80202	Fax:	720-876-6060
5. API Number	05-045-12195	OGCC Facility ID Number	
6. Well/Facility Name:	Keinath	7. Well/Facility Number	33-16 (OP33)
8. Location (Qtr/Qtr, Sec, Twp, Rng, Meridian):	SESE Sec 33-T7S-R9&W 6th PM		
9. County:	Garfield	10. Field Name:	Parachute
11. Federal, Indian or State Lease Number:			

Complete the Attachment Checklist

OP OGCC

Survey Plat	
Directional Survey	
Surface Eqmnt Diagram	
Technical Info Page	X
Other	

General Notice

<input type="checkbox"/> CHANGE OF LOCATION:	Attach New Survey Plat	(a change of surface qtr/qtr is substantive and requires a new permit)
Change of Surface Footage from Exterior Section Lines:		FNL/FWL
Change of Surface Footage to Exterior Section Lines:		
Change of Bottomhole Footage from Exterior Section Lines:		
Change of Bottomhole Footage to Exterior Section Lines:		
Bottomhole location Qtr/Qtr, Sec, Twp, Rng, Mer		attach directional survey
Latitude		
Longitude		
Ground Elevation		
	Distance to nearest property line	Distance to nearest bldg, public rd, utility or RR
	Distance to nearest lease line	Is location in a High Density Area (rule 603b)? Yes/No
	Distance to nearest well same formation	Surface owner consultation date:

GPS DATA:

Date of Measurement PDOP Reading Instrument Operator's Name

<input type="checkbox"/> CHANGE SPACING UNIT		<input type="checkbox"/> Remove from surface bond
Formation	Spacing order number	Signed surface use agreement attached

<input type="checkbox"/> CHANGE OF OPERATOR (prior to drilling):	<input type="checkbox"/> CHANGE WELL NAME	NUMBER
Effective Date:	From:	
Plugging Bond:	To:	
<input type="checkbox"/> Blanket <input type="checkbox"/> Individual	Effective Date:	

<input type="checkbox"/> ABANDONED LOCATION:	<input type="checkbox"/> NOTICE OF CONTINUED SHUT IN STATUS
Was location ever built? <input type="checkbox"/> Yes <input type="checkbox"/> No	Date well shut in or temporarily abandoned:
Is site ready for inspection? <input type="checkbox"/> Yes <input type="checkbox"/> No	Has Production Equipment been removed from site? <input type="checkbox"/> Yes <input type="checkbox"/> No
Date Ready for inspection:	MIT required if shut in longer than two years. Date of last MIT

<input type="checkbox"/> SPUD DATE:	<input type="checkbox"/> REQUEST FOR CONFIDENTIAL STATUS (6 mos from date casing set)
-------------------------------------	---

<input type="checkbox"/> SUBSEQUENT REPORT OF STAGE, SQUEEZE OR REMEDIAL CEMENT WORK	*submit cbl and cement job summaries
Method used	Cementing tool setting/perf depth
Cement volume	Cement top
Cement bottom	Date

<input type="checkbox"/> RECLAMATION:	Attach technical page describing final reclamation procedures per Rule 1004.
Final reclamation will commence on approximately	<input type="checkbox"/> Final reclamation is completed and site is ready for inspection.

Technical Engineering/Environmental Notice

<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Report of Work Done
Approximate Start Date:	Date Work Completed:

Details of work must be described in full on Technical Information Page (Page 2 must be submitted.)	
<input type="checkbox"/> Intent to Recomplete (submit form 2)	<input type="checkbox"/> Request to Vent or Flare
<input type="checkbox"/> Change Drilling Plans	<input checked="" type="checkbox"/> Repair Well
<input type="checkbox"/> Gross Interval Changed?	<input type="checkbox"/> Rule 502 variance requested
<input type="checkbox"/> Casing/Cementing Program Change	<input type="checkbox"/> Other:
<input type="checkbox"/> E&P Waste Disposal	<input type="checkbox"/> Beneficial Reuse of E&P Waste
<input type="checkbox"/> Status Update/Change of Remediation Plans	for Spills and Releases

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.

Signed: DeAnne Spector Date: 3/23/09 Email: deanne.spector@encana.com

Print Name: DeAnne Spector Title: Regulatory Analyst

COGCC Approved: Keith Kij Title: EIT III Date: MAR 31 2010

CONDITIONS OF APPROVAL, IF ANY:

TECHNICAL INFORMATION PAGE



FOR OGCC USE ONLY

RECEIVED
MAR 25 2010
COGCC/Rifle Office

1. Operator Number:	100185	API Number:	05-045-12195
2. Name of Operator:	ENCANA OIL & GAS (USA) INC.		
3. Well Name:	Keinath	Well Number:	33-16 (OP33)
4. Location (Qtr/Ctr, Sec, Twp, Rng, Meridian):	SESE, Sec 33-T7S-R96W 6th PM		

This form is to be completed whenever a Sundry Notice is submitted requiring detailed report of work to be performed or completed. This form shall be transmitted within 30 days of work completed as a "subsequent" report and must accompany Form 4, page 1.

5

DESCRIBE PROPOSED OR COMPLETED OPERATIONS

EnCana Oil & Gas (USA) Inc. requests approval to trip tubing and replace damaged/corroded and sanded off joints of tubing.

HIT confirmed, S/L tagged ~ 700' sand in tbg.

Procedure:

1. MIRU pulling unit.
2. Top kill well if necessary, ND WH, NU BOPs.
3. RIH w/ tbg, confirm PBTD at 5445'; if fill is encountered, check w/ Denver for c/o procedure.
4. Rig up ScanTech and scan tbg out to check for damage/scale, **replace where necessary.**

***Please make note of the depth of the hole(s) and send in for analysis.**

5. POOH w/ 2-3/8" 4.7# N-80 EUE tbg, plus the tag jts.
6. Lay down sanded tbg.
7. If scale is found, RIH w/ full gauge mill to PBTD.

Call Denver for acid procedure (if scale found).

8. RIH w/ 2-3/8" 4.7# N-80 EUE, land EOT @ ~4350' - (Confirm prior to setting).
9. Place well back on production.
10. RDMO

Call Craig Miley @ (303) 495-8665 if there are any questions.