

FORM  
2

Rev  
12/05

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Document Number:

400071085

Plugging Bond Surety

20100082

APPLICATION FOR PERMIT TO:

1. ☒ Drill, ☐ Deepen, ☐ Re-enter, ☐ Recomplete and Operate

2. TYPE OF WELL

OIL ☒ GAS ☐ COALBED ☐ OTHER \_\_\_\_\_  
SINGLE ZONE ☒ MULTIPLE ZONE ☐ COMMINGLE ZONE ☐

Refiling ☐

Sidetrack ☐

3. Name of Operator: SLAWSON EXPLORATION COMPANY INC

4. COGCC Operator Number: 10334

5. Address: 1675 BROADWAY - SUITE 1600

City: DENVER State: CO Zip: 80202

6. Contact Name: Terry Hoffman Phone: (303)250-0619 Fax: (303)412-8212  
Email: tlhoffman@q.com

7. Well Name: Pickeroon Well Number: 36-12-66

8. Unit Name (if appl): \_\_\_\_\_ Unit Number: \_\_\_\_\_

9. Proposed Total Measured Depth: 12945

WELL LOCATION INFORMATION

10. QtrQtr: NWNW Sec: 36 Twp: 12N Rng: 66W Meridian: 6

Latitude: 40.969690 Longitude: -104.731580

Footage at Surface: 605 FNL/FSL FNL 606 FEL/FWL FWL

11. Field Name: Wildcat Field Number: 99999

12. Ground Elevation: 6176 13. County: WELD

14. GPS Data:

Date of Measurement: 04/28/2010 PDOP Reading: 2.3 Instrument Operator's Name: Daniel King

15. If well is ☐ Directional ☒ Horizontal (highly deviated) **submit deviated drilling plan.**

Footage at Top of Prod Zone: FNL/FSL 1054 FNL 765 FWL 650 FSL 1998 FWL 650  
Sec: 36 Twp: 12N Rng: 66W Sec: 36 Twp: 12N Rng: 66W

16. Is location in a high density area? (Rule 603b)? ☐ Yes ☒ No

17. Distance to the nearest building, public road, above ground utility or railroad: 5280 ft

18. Distance to nearest property line: 827 ft 19. Distance to nearest well permitted/completed in the same formation: 5280 ft

20. LEASE, SPACING AND POOLING INFORMATION

Objective Formation(s)	Formation Code	Spacing Order Number(s)	Unit Acreage Assigned to Well	Unit Configuration (N/2, SE/4, etc.)
Niobrara	NBRR		640	ALL

21. Mineral Ownership: ☐ Fee ☒ State ☐ Federal ☐ Indian Lease #: 8765.5

22. Surface Ownership: ☒ Fee ☐ State ☐ Federal ☐ Indian

23. Is the Surface Owner also the Mineral Owner? ☐ Yes ☒ No Surface Surety ID#: 20100120

23a. If 23 is Yes: Is the Surface Owner(s) signature on the lease? ☐ Yes ☐ No

23b. If 23 is No ☐ Surface Owners Agreement Attached or ☒ \$25,000 Blanket Surface Bon ☐ \$2,000 Surface Bond ☐ \$5,000 Surface Bond

24. Using standard QtrQtr, Sec, Twp, Rng format enter entire mineral lease description upon which this proposed wellsite is located (attach separate sheet/map if you prefer):  
T12N,R66W, Section 36: All

25. Distance to Nearest Mineral Lease Line: 650 ft 26. Total Acres in Lease: 640

### DRILLING PLANS AND PROCEDURES

27. Is H2S anticipated? ☐ Yes ☒ No If Yes, attach contingency plan.

28. Will salt sections be encountered during drilling? ☐ Yes ☒ No

29. Will salt (>15,000 ppm TDS CL) or oil based muds be used during drilling? ☐ Yes ☒ No

30. If questions 27 or 28 are yes, is this location in a sensitive area (Rule 903)? ☐ Yes ☒ No If 28, 29, or 30 are "Yes" a pit permit may be required.

31. Mud disposal: ☐ Offsite ☒ Onsite

Method: ☐ Land Farming ☒ Land Spreading ☐ Disposal Facility Other: \_\_\_\_\_

Note: The use of an earthen pit for Recompletion fluids requires a pit permit (Rule 905b). If air/gas drilling, notify local fire officials.

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Bottom	Cement Top
SURF	13+1/2	9+5/8	36	2,575	757	2,575	0
1ST	8+3/4	7	26	9,206	180	9,206	7,400
1ST LINER	6	4+1/2	11.6	12,915	0		

32. BOP Equipment Type: ☒ Annular Preventer ☒ Double Ram ☒ Rotating Head ☐ None

33. Comments No conductor will be set on this well. Any measurement 5280' is 1 mile or greater. Surface Surety Bond # missing in Sec III, item #22. Returned to draft for operator to correct. SF 6/30/10

34. Location ID: \_\_\_\_\_

35. Is this application in a Comprehensive Drilling Plan ? ☐ Yes ☒ No

36. Is this application part of submitted Oil and Gas Location Assessment ? ☒ Yes ☐ No

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Terry L. Hoffman

Title: Permit Agent Date: 7/28/2010 Email: tlhoffman@q.com

Based on the information provided herein, this Application for Permit-to-Drill complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: David S. Neslin Director of COGCC Date: 8/13/2010

#### API NUMBER

05 123 31984 00

Permit Number: \_\_\_\_\_ Expiration Date: 8/12/2012

CONDITIONS OF APPROVAL, IF ANY: \_\_\_\_\_

All representations, stipulations and conditions of approval stated in the Form 2A for this location shall constitute representations, stipulations and conditions of approval for this Form 2 Permit-to-Drill and are enforceable to the same extent as all other representations, stipulations and conditions of approval stated in this Permit-to-Drill.

- 1) Note surface casing setting depth change from 2524' to 2575'. Increase cement coverage accordingly.
- 2) Provide 24 hour notice of MIRU to Ed Binkley at 970-506-9834 or e-mail at ed.binkley@state.co.us
- 3) Comply with Rule 317.i and provide cement coverage from bottom of production casing to a minimum of 200' above Niobrara. Verify coverage with cement bond log.
- 4) Run and submit Directional Survey from TD to base of surface casing. The operator shall comply with Rule 321, and it shall be the operator's responsibility to ensure that the wellbore complies with setback requirements in commission orders or rules prior to producing the well.

### **Attachment Check List**

Att Doc Num	Name	Doc Description
1770470	SURFACE CASING CHECK	LF@2511704 1770470
400071085	FORM 2 SUBMITTED	LF@2499595 400071085
400071120	WELL LOCATION PLAT	LF@2499596 400071120
400071146	DEVIATED DRILLING PLAN	LF@2499597 400071146
400073379	30 DAY NOTICE LETTER	LF@2499598 400073379

Total Attach: 5 Files

### **General Comments**

<b><u>User Group</u></b>	<b><u>Comment</u></b>	<b><u>Comment Date</u></b>
Permit	Surface Restoration Bond on file with SLB, per Sherry Lee. PVG	8/12/2010 4:59:39 PM

Total: 1 comment(s)

Error: Subreport could not be shown.