



Andrews, David

From: Andrews, David
Sent: Tuesday, November 30, 2010 11:20 AM
To: 'Soehner, Gage A.'; King, Kevin
Cc: Spector, DeAnne M.; McGilvery, Ryan; Pfister, Miracle
Subject: RE: Twin Creek 1-9C1 (O1EB) Production Casing Temperature Log (API# 05-045-19511)

Gage,

You are approved to delay the CBL on Twin Creek 1-9C1 (O1EB). Please reply with corrections to two inconsistencies in your email below regarding well numbers (i.e., 12-2A1 vs. 12-2D1 and 1-9C1 vs. 1-9A1).

Thanks,

David D. Andrews, P.E., P.G.
Engineering Supervisor - Western Colorado

State of Colorado
Oil and Gas Conservation Commission
707 Wapiti Court, Suite 204
Rifle, Colorado 81650
Office Phone: (970) 625-2497 Ext. 1
Cell Phone: (970) 456-5262
Fax: (970) 625-5682
E-mail: David.Andrews@state.co.us
Website: <http://www.colorado.gov/cogcc>

UPON FURTHER REVIEW, NO
INCONSISTENCIES NOTED. FIVE
DIFFERENT WELLS ARE
SHOWN BELOW.

D.A.

From: Soehner, Gage A. [<mailto:Gage.Soehner@encana.com>]
Sent: Wednesday, November 24, 2010 4:29 PM
To: Andrews, David; King, Kevin
Cc: Spector, DeAnne M.; McGilvery, Ryan; Pfister, Miracle
Subject: Twin Creek 1-9C1 (O1EB) Production Casing Temperature Log (API# 05-045-19511)

Kevin,

Attached is the temperature log run in place of the 12 to 48 hour CBL on the Twin Creek 1-9C1 well drilled by Nabors M15. This is the ninth of fifteen production holes to be drilled on the pad after the completion of the surface casing batch set operation.

The production casing was cemented on 11/16/10 with the plug bumping at 4:15 PM on 11/16/10. This was a two-stage cement operation with the stage tool set at 3362 ' MD. Both stages had full circulation and were successful. The second stage brought 60 bbls of cement to surface.

TOG on this well was 4,191' MD. Designed TOC was 639 ' & the TOC according to the temp log is 660' MD.

Bradenhead pressure on this well is as follows:

6 hrs	0 psi
12 hrs	0 psi
24 hrs	95 psi
72 hrs	100 psi

Today, this brings the total count to three for wells with bradenhead pressure on the O1EB pad:

Twin Creek 1-10C1 50psi Continuous bleed down to flare 045-19549

Twin Creek 12-2A1	30 psi	No bleed down	045-19548
TwinCreek 1-9C1	95 psi	No bleed down	045-19511

As you may notice, the Twin Creek 12-2D1 and the Twin Creek have 1-9A1 have gone to zero and not built pressure up again. We will continue to monitor bradenhead pressure hourly, bleeding off as necessary to keep under 150 psi until the CBL's are run after the rig has moved off of the pad.

Thanks,

Gage Soehner
Encana Oil & Gas
Drilling Engineer
South Piceance
720.876.3097
720.951.0732 Cell

045-19527

045-19543

This email communication and any files transmitted with it may contain confidential and or proprietary information and is provided for the use of the intended recipient only. Any review, retransmission or dissemination of this information by anyone other than the intended recipient is prohibited. If you receive this email in error, please contact the sender and delete this communication and any copies immediately. Thank you.

<http://www.encana.com>