

KINDER MORGAN CO2 COMPANY LP

Goodman Point - 16 surface location

640 FNL & 632 FWL

Section 33 T.37 N. R.17 W. NMPM


Montezuma County CO

6734' grd el from GPS

2638 FSL & 627' FWL bottom hole

Section 33 T.37 N. R.17 W. NMPM

Montezuma County CO



Date of survey: 01/23/08

Date of plat 01/27/08

The above is true and correct to my knowledge and belief