

FORM  
6  
Rev  
12/05

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80205 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Date Received:  
10/15/2010

Document Number:  
1770640

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set.

A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 69200 Contact Name: ROBERT JULANDER  
Name of Operator: PETROLEUM ENERGY CORP Phone: (303) 758-1113  
Address: 90 SILVER FOX DR Fax: (303) 955-5077  
City: GREENWOOD VILL State: CO Zip: 80121  
24 hour notice required, contact: Name: Bo Brown Tel: (970) 330-6085

API Number: 05-123-10007-00 Well Name: SPEAKER Well Number: D  
Location: QtrQtr: NWNW Section: 35 Township: 8N Range: 61W Meridian: 6  
County: WELD Federal, Indian or State Lease Number:  
Field Name: NIGHTHAWK Field Number: 57370

Notice of Intent to Abandon  Subsequent Report of Abandonment

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.623780 Longitude: -104.180320  
GPS Data:  
Data of Measurement: 04/14/2006 PDOP Reading: 2.5 GPS Instrument Operator's Name: Steve Fisher  
Reason for Abandonment:  Dry  Production for Sub-economic  Mechanical Problems  
 Other  
Casing to be pulled:  Yes  No Top of Casing Cement:  
Fish in Hole:  Yes  No If yes, explain details below  
Wellbore has Uncemented Casing leaks:  Yes  No If yes, explain details below  
Details:

Current and Previously Abandoned Zones

Formation	Code	Perf. Top	Perf. Bottom	Date	Method of Isolation	Plug Depth
D SAND	DSND	7058	7063			

Total: 1 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Weight Per Foot	Setting Depth	Sacks Cement	Cement Top	Cement Bot	Status
SURF	12+1/4	8+5/8	24	134	150	0	134	
1ST	7+7/8	4+1/2	11.6	7,191	265	5,910	7,191	CBL

## Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIBP #2: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #3: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top. CIBP #4: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.  
CIBP #5: Depth \_\_\_\_\_ with \_\_\_\_\_ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 25 sks cmt from 7070 ft. to 6770 ft. in Plug Type: CASING Plug Tagged:  
Set 25 sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. in Plug Type: STUB PLUG Plug Tagged:  
Set 50 sks cmt from 580 ft. to 480 ft. in Plug Type: OPEN HOLE Plug Tagged:  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. in Plug Type: \_\_\_\_\_ Plug Tagged:  
Set \_\_\_\_\_ sks cmt from \_\_\_\_\_ ft. to \_\_\_\_\_ ft. in Plug Type: \_\_\_\_\_ Plug Tagged:  
Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth  
Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth  
Perforate and squeeze at \_\_\_\_\_ ft. with \_\_\_\_\_ sacks. Leave at least 100 ft. in casing \_\_\_\_\_ CICR Depth  
(Cast Iron Cement Retainer Depth)  
Set 40 sacks half in. half out surface casing from 180 ft. to 50 ft. Plug Tagged:  
Set 10 sacks at surface  
Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker:  Yes  No  
Set \_\_\_\_\_ sacks in rat hole Set \_\_\_\_\_ sacks in mouse hole

### Additional Plugging Information for Subsequent Report Only

Casing Recovered: \_\_\_\_\_ ft. of \_\_\_\_\_ inch casing Plugging Date: \_\_\_\_\_  
\*Wireline Contractor: \_\_\_\_\_ \*Cementing Contractor: \_\_\_\_\_  
Type of Cement and Additives Used: \_\_\_\_\_  
Flowline/Pipeline has been abandoned per Rule 1103  Yes  No

Provide Technical Detail:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: ROBERT C. JULANDER  
Title: VICE PRESIDENT Date: 9/10/2010 Email: RJULANDER@Q.COM

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: David S. Neslin D.B. **Director of COGCC** Date: 12/28/2010  
BURN, DIANA

**CONDITIONS OF APPROVAL, IF ANY:**

Expiration Date: 6/27/2011

### Attachment Check List

Att Doc Num	Name
1770640	FORM 6 INTENT SUBMITTED
2512767	SURFACE CASING CHECK

Total Attach: 2 Files

### General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>

Total: 0 comment(s)