

CHEVRON USA, INC.


BOTTOM HOLE DIAGRAM FOR

FEE #160X & #161X
SECTION 28, T2N, R102W, 6th P.M.
SE 1/4 SE 1/4

FIGURE #5

DATE: 11-19-10
DRAWN BY: S.L.

NE Cor. Sec. 28
2007 Alum. Cap,
0.4' High
Lat: 40.121306°
Long: 108.838856°



28

1/4 Section Line

1/4 Section Line

1/16 Section Line


1/16 Section Line

SE 1/4

27

W.C.
Alum. Cap, 1.0' High
Lat: 40.113706°
Long: 108.838856°

True Position



FEE #160X
BOTTOM HOLE
(1461' FSL 235' FWL)

SW 1/4

SW Cor. Sec. 28
Found Steel Pipes,
Set New 2008
Alum. Cap, RLS
#17492, 1.2' High,
Lat: 40.106800°
Long: 108.857761°

FEE #161X
BOTTOM HOLE
(30' FSL 1075' FEL)

Section Line

N87°43'15"W - 5288.15' (Meas.)

Alum. Cap, 0.3'
High, Pile of Stones
Lat: 40.106761°
Long: 108.838861°

N87°54'23"W
2669.97' (Meas.)

S 1/4 Cor. Sec. 27
2007 Alum. Cap,
0.4' High, Steel Post
Lat: 40.106764°
Long: 108.829319°

N02°09'35"E
2530.69' (Meas.)

N46°26'44"E
970.41'

S44°38'54"W
961.26'



NE 1/4

UINTAH ENGINEERING & LAND SURVEYING
85 So. 200 East * Vernal, Utah 84078 * (435) 789-1017

