



DEPARTMENT OF NATURAL RESOURCES

Bill Ritter, Jr., Governor
1120 Lincoln St. Suite 801
Denver, CO 80203
Phone: (303) 894-2100
FAX: (303) 894-2109
www.colorado.gov/cogcc

January 13, 2011

MRS. VICKIE J. KURRASCH
CHEVRON PROD CO
HES - Oil Area Operations

Re: Weber Sand Unit NGL/CO2 Plant
Groundwater Monitoring Report
COGCC REM #533

Dear Mrs. Kurrasch,

Colorado Oil and Gas Conservation Commission (COGCC) staff is reviewing documentation concerning outstanding case closure and/or remediation issues across the state. On August 01, 2000, Chevron submitted a Form 27 Site Investigation and Remediation Work Plans in relation to a spill/release that occurred at the above referenced site. Groundwater monitoring reports were submitted quarterly and then annually until 2008. According to the last GW monitoring report on record at COGCC, submitted by Cordilleran on behalf of Chevron, benzene concentrations of 4,000 and 700 ug/L were measured at monitoring wells MW-7 and MW-11 respectively. Cordilleran proposed to continue GW monitoring until BTEX concentrations were below Table 910-1 values.

Would you please re-submit the 2009 and 2010 groundwater monitoring reports for our review? If monitoring of natural attenuation has been discontinued, please provide an explanation.

If you require any additional information, please call me at (970) 625-2497.

Sincerely,

Carlos A. Luján for
Chris Canfield
Environmental Protection Specialist, NW Region

Cc: Debbie Baldwin – COGCC Environmental Manager
Alex Fischer – COGCC Environmental Supervisor